

400 South Fourth Street Suite 712 Minneapolis MN 55415 P 612.341.4051 • F 612.337.5843 • www.mmarchltd.com

Stuart MacDonald Robert Mack Todd Grover Angela Wolf Scott

Memorandum

Date October 14, 2020

To MNHS Legacy Grant Review

From Charles Thompson Memorial Hall and MacDonald & Mack

Project Charles Thompson Memorial Hall Restoration and Elevator Addition


Regarding 30% Review

Please see the attached documents for the updated designs of the Charles Thompson Memorial Hall and Elevator Addition. Included are:

- 30% Presentation Documents presented to Charles Thompson Memorial Hall
- 30% Construction Drawings
- 30% Specification Outline
- 30% HVAC, Electrical, and Plumbing Scope Narrative

From the designs included in the HSR, these drawings are the next level of development for the work at the building. Changes include:

- Revised restroom drawings on the Lower Level and First Floor
- Updated restoration of the exterior of the Hall, including the North Porch
 - o Guardrails are added to the historic railing configuration because the current railings will be removed and as this exit serves as an egress, the higher railings will be required by code.
 - Additional investigation of the areas of masonry repair were added to the drawings.
- Revised plan of the elevator addition.
 - o The plan is slightly larger to allow for a better connection to the existing building, a better use of space in the addition, and to provide additional storage and meeting space desperately needed in the building.
 - o The elevations are a bit more contemporary. This was the outcome of massing and window studies and to avoid a direct duplication of the historic configuration and details of the existing Hall. The details are simplified with grouped windows to keep with a similar, compatible scale.



SITE PLAN
SCALE: 1" = 10"



MACDONALD & MACK A R C H I T E C T S 4 0 0 SOUTH FOURTH STREET STE 7 1 2 MINNEAPOLIS MINNESOTA 5 5 4 1 5 P 6 1 2 3 4 1 4 0 5 1 F 6 1 2 3 3 7 5 8 4 3 WWW MMARCHITD COM


Charles Thompson Memorial Hall


1824 Marshal Avenue Saint Paul, MN

DATE September 14, 2020 REVISED DRAWN to

Site Plan

6





MACDONALD & MACK 4 0 0 SOUTH FOURTH STREET STE 7 1 2 MINNEAPOLIS MINNESOTA 5 5 4 1 5

612 341 4051 • F612 337 5843 • WWW.MMARCHLTD.COM


1824 Marshal Avenue Saint Paul, MN

September 14, 2020 REVISED

DRAWN tag

APPROVED

Basement Plan





MACDONALD & MACK


4 0 0 SOUTH FOURTH STREET STE 7 1 2 MINNEAPOLIS MINNESOTA 5 5 4 1 5 0 612 341 4051 • F 612 337 5843 • WWW.MMARCHLTD.COM

1824 Marshal Avenue Saint Paul, MN

September 14, 2020 REVISED

DRAWN tag APPROVED

First Floor Plan






MACDONALD & MACK
A R C H I T E C T S


4 0 0 SOUTH FOURTH STREET STE 7 1 2 MINNEAPOLIS MINNESOTA 5 5 4 1 5

612 341 4051 • F612 337 5843 • WWW.MMARCHLTD.COM

1824 Marshal Avenue Saint Paul, MN

DATE September 14, 2020 REVISED DRAWN tag APPROVED Second Floor Plan






MACDONALD & MACK A R C H I T E C T S

612 341 4051 • F612 337 5843 • WWW.MMARCHLTD.COM

Charles Thompson Memorial Hall

1824 Marshal Avenue Saint Paul, MN

DATE September 14, 2020 REVISED DRAWN tag APPROVED Third Floor Plan





Charles Thompson Memorial Hall

1824 Marshal Avenue Saint Paul, MN


D A T E September 14, 2020 R E V I S E D D R A W N A P P R O V E D Entry Section





Charles Thompson Memorial Hall Rehabilitation, HVAC Upgrade, and Addition

1824 Marshall Avenue, Saint Paul, MN 55104



1 LOCATION MAP G000 NO SCALE

GENERAL NOTES:

The building is to be fully protected from damage during the course of construction. All damaged areas and finishes resulting from this work are to be restored by the contractor to match existing construction.

The contractor shall verify all existing conditions and dimensions in the field before beginning work.

The contractor shall immediately report any discrepancies between drawings and existing conditions and dimensions to the architect for resolution.

Do not scale drawings.

Where "repair" or "in-fill" is indicated on the drawings, the repair or in-fill item is to match and blend with adjacent surfaces and features in all respects.

PROJECT CONTACTS:

Owner Representative Herman Fuechtmann Charles Thompson Memorial Hall 1824 Marshall Avenue Saint Paul, MN 55104 Email: hermanfuechty@gmail.com

MacDonald & Mack Architects, Ltd. 400 South Fourth Street, Suite 712 Minneapolis, MN 55415 T: 612.341.4051 F: 612.337.5843

Collaborating Architect
Gregg Hackett Gregg Hackett Architect 4342 Abbott Avenue South Minneapolis, MN 55410 T: 612.708.7584

Structural Engineering Ken Green Mattson Macdonald Young, Inc. 901 North Third Street, Suite 100 Minneapolis, MN 55401 T: 612.827.7825 F: 612.827.0805

Mechanical, Electrical, and Plumbing Engineering Hallberg Engineering 1750 Commerce Court White Bear Lake, MN 55110


Anderson Engineering 13605 First Avenue North, #100 Plymouth, MN 55441 T: 763.412.4022

T: 651.748.1100

Elevator Kathy Markwell Elevator Advisory Group, Inc. 14530 Pennock Avenue, Suite 104 Apple Valley, MN 55124 T: 952.432.4443 F: 952.432.4449

Discipline	Sheet No.	Sheet Name
GENERAL	G000	COVER SHEET
CIVIL	C000	
LANDSCAPE	L000	
ARCHITECTURE	A001	LIFE SAFETY PLAN
ARCHITECTURE	A002	NOTES
ARCHITECTURE	A050	DEMOLITION SITE PLAN
ARCHITECTURE	A100	LOWER LEVEL DEMOLITION PLAN
ARCHITECTURE	A101	FIRST FLOOR DEMOLITION PLAN
ARCHITECTURE	A102	SECOND FLOOR DEMOLITION PLAN
ARCHITECTURE	A103	THIRD FLOOR DEMOLITION PLAN
ARCHITECTURE	A104	ROOF DEMOLITION PLAN
ARCHITECTURE	A105	RCP LOWER LEVEL DEMOLITION
ARCHITECTURE	A106	RCP FIRST FLOOR DEMOLITION
ARCHITECTURE	A107	RCP SECOND FLOOR DEMOLITION
ARCHITECTURE	A108	RCP THIRD FLOOR DEMOLITION
ARCHITECTURE	A200	LOWER LEVEL CONSTRUCTION PLAN
ARCHITECTURE	A201	FIRST FLOOR CONSTRUCTION PLAN
ARCHITECTURE	A202	SECOND FLOOR CONSTRUCTION PLAN
ARCHITECTURE	A203	THIRD FLOOR CONSTRUCTION PLAN
ARCHITECTURE	A204	ROOF CONSTRUCTION PLAN
ARCHITECTURE	A205	LOWER LEVEL RCP
ARCHITECTURE	A206	FIRST FLOOR RCP
ARCHITECTURE	A207	SECOND FLOOR RCP
ARCHITECTURE	A208	THIRD FLOOR RCP
ARCHITECTURE	A300	NORTH DEMOLITION ELEVATION
ARCHITECTURE	A301	EAST DEMOLITION ELEVATION
ARCHITECTURE	A302	SOUTH DEMOLITION ELEVATION
ARCHITECTURE	A303	WEST DEMOLITION ELEVATION
ARCHITECTURE	A304	NORTH CONSTRUCTION ELEVATION
		EAST CONSTRUCTION ELEVATION
ARCHITECTURE	A305	
ARCHITECTURE	A306	SOUTH CONSTRUCTION ELEVATION
ARCHITECTURE	A307	WEST CONSTRUCTION ELEVATION
ARCHITECTURE	A320	BUILDING SECTIONS
ARCHITECTURE	A400	INTERIOR ELEVATIONS
ARCHITECTURE	A401	INTERIOR ELEVATIONS
ARCHITECTURE	A402	INTERIOR ELEVATIONS
ARCHITECTURE	A403	INTERIOR ELEVATIONS
ARCHITECTURE	A404	INTERIOR ELEVATIONS
ARCHITECTURE	A430	SIGNAGE PLANS AND SCHEDULE
ARCHITECTURE	A440	STAIR SECTIONS AND DETAILS
ARCHITECTURE	A500	WALL SECTIONS AND DETAILS
ARCHITECTURE	A501	WALL SECTIONS AND DETAILS
ARCHITECTURE	A502	WALL SECTIONS AND DETAILS
ARCHITECTURE	A503	PORCH DETAILS
ARCHITECTURE	A503 A504	ROOF AND EXTERIOR REPAIR DETAILS
ARCHITECTURE	A505	WINDOW AND DOOR DETAILS
ARCHITECTURE	A506	GENERAL DETAILS
ARCHITECTURE	A600	WALL TYPES
ARCHITECTURE	A601	SCHEDULES
ARCHITECTURE	A602	SCHEDULES
STRUCTURAL		
PLUMBING		
MECHANICAL		
ELECTRICAL		

DRAWING INDEX



COVER SHEET

OCCUPANCY GROUPS/LOADING SUMMARY FOR SECOND FLOOR

APPLICABLE CODES

2020 Minnesota State Building Code 2020 Minnesota Conservation Code for Existing Buildings

2020 Minnesota Accessibility Code

 2020 Minnesota Energy Code • 2020 Minnesota Fire Code

 2017 National Electrical Code (NFPA 70-2017) Minnesota Electrical Code

 2020 Minnesota Mechanical and Fuel Gas Code (2012 International Mechanical Code with MN Amendments) • 2015 Minnesota Plumbing Code

 NFPA 13 Installation of Fire Sprinklers City of Saint Paul Zoning Code

Heritage Preservation Commission Regulations of the City of Saint Paul

BUILDING INFORMATION: 4 Stories: Lower Level, First Floor, Second Floor, and Third Floor, Main Entrance on First Floor Existing Parking Lot to be Reconfigured Third Floor: GSF

GSF

GSF

Lower Level: GSF TYPE OF CONSTRUCTION:

Second Floor:

First Floor:

Type III-B; Not Sprinkled Proposed construction will be fully sprinkled

PLUMBING FIXTURES:

EGRESS REQUIREMENTS:

ONALD

1 | LOWER LEVEL LIFE SAFETY PLAN

A001 1/8" = 1'-0"

OCCUPANCY GROUPS/LOADING SUMMARY FOR FIRST FLOOR
Office
Addition Lobby
Billard Room

OCCUPANCY GROUPS/LOADING SUMMARY FOR LOWER LEVEL

121.8sf

180sf 282sf

1103.5sf

50/sf

60/sf 15/sf 300/sf Total

15/sf

A-2 Addition Lobby

A-2 Kitchen (Serving)

A-2 Card Room

Boiler Room

A-2 Lower Level Social Hall

3 | SECOND FLOOR LIFE SAFETY PLAN

A001 1/8" = 1'-0"

OCCUPANCY GROUPS/LOADING SUMMARY FOR THIRD FLOOR

Charles Thompson Memorial Hall Rehabilitation, HVAC Upgrade, and Addition

LIFE SAFETY PLAN

30% REVIEW SET

2 | FIRST FLOOR LIFE SAFETY PLAN A001 1/8" = 1'-0"

4 THIRD FLOOR LIFE SAFETY PLAN A001 1/8" = 1'-0"

30% REVIEW SET

A002

NOTES

FAIRVIEW AVENUE NORTH

- \bigcirc REMOVE AND SALVAGE LIGHT POSTS.

- (6) DISMANTLE PIERS, INCLUDING CONCRETE BASES. SALVAGE BRICK.
- BASE TO REMAIN.
- 8 DEMOLISH SIDEWALK (CITY SIDEWALK TO REMAIN).
- 9 remove brick infill in Porch openings and DEMOLISH CONCRETE INFILL. TAKE CARE NOT TO DAMAGE ORIGINAL SURROUNDING MASONRY AND CONCRETE.
- 10 DEMOLISH WALL AND NOTIFY ARCHITECT. ARCHITECT TO INSPECT AREA BENEATH STAIRS BEFORE INFILLED.
- SALVAGE STONE BENEATH FOR REINSTALLATION.
- (13) SALVAGE DOOR FOR REINSTALLATION.
- STALL DOORS.
- STRUCTURAL DRAWINGS FOR EXTENT BELOW GRADE.
- (19) SALVAGE WINDOW GLAZING AND FRAME, RETURN TO OWNER. SELECTIVELY REMOVE PORTION OF EXTERIOR
- 20 REMOVE WALL.
- $\langle 21 \rangle$ REMOVE DOOR.

- 26 REMOVE LIGHT FIXTURE.

DEMOLISH MASONRY, SALVAGE AS NOTED REMOVE/DISMANTLE




(10% REPOINTING, TYPICAL)

SITE PLAN

30% REVIEW SET

1 DEMOLITION SITE PLAN A050 | 1/8" = 1'-0"



 $\langle 2 \rangle$ remove porch railings and stair handrails.

3 REMOVE AND SALVAGE STONE STEPS.

 $\langle 4 \rangle$ remove quarry tiles, salvage where possible.

(5) REMOVE MESH SCREEN AND SALVAGE FRAME.

 $\langle 7 \rangle$ dismantle stair walls. Salvage brick and dispose OF CAST STONE CAPS. CONCRETE FOUNDATION AND ONALD

HaH

Charles Thompson Memorial Rehabilitation, HVAC Upgrade, and Addition

(11) INSTALL TEMPORARY SHORING AT PORCH ROOF AND DEMOLISH COLUMNS. SALVAGE CAST STONE BASES FOR REINSTALLATION.

12) REMOVE CAST STONE AT PORCH EDGE. REMOVE AND

14) REMOVE ALL EXISTING TOILET ROOM PARTITIONS AND

(15) REMOVE TOILET ROOM FIXTURES.

16) remove walls and concrete at grade. See

(17) REMOVE METAL BARS FROM WINDOWS.

(18) REMOVE WINDOW INFILL PANELS.

WALL NECESSARY TO RECEIVE DOOR.

 $\langle 22 \rangle$ remove radiator.

23 REMOVE KITCHEN APPLIANCES AND SINK.

(24) REMOVE COUNTERTOPS.

25) REMOVE CEILING TILES.

27) DEMOLISH GARAGE.

REMOVAL KEY

DEMOLISH MASONRY, SALVAGE AS NOTED BRICK MASONRY TO REMAIN

DEMOLITION

1 LOWER LEVEL DEMOLITION PLAN A100 1/4" = 1'-0"

REMOVAL NOTES

- $\langle 1 \rangle$ remove and salvage light posts.

- $\overline{\langle 4 \rangle}$ remove quarry tiles, salvage where possible.
- OF CAST STONE CAPS. CONCRETE FOUNDATION AND BASE TO REMAIN.
- 8 DEMOLISH SIDEWALK (CITY SIDEWALK TO REMAIN).
- 9 REMOVE BRICK INFILL IN PORCH OPENINGS AND CONCRETE.
- 10 DEMOLISH WALL AND NOTIFY ARCHITECT. ARCHITECT TO INSPECT AREA BENEATH STAIRS BEFORE INFILLED.
- DEMOLISH COLUMNS. SALVAGE CAST STONE BASES FOR REINSTALLATION.
- (12) REMOVE CAST STONE AT PORCH EDGE. REMOVE AND SALVAGE STONE BENEATH FOR REINSTALLATION.
- $\langle 13 \rangle$ Salvage door for reinstallation.
- (15) REMOVE TOILET ROOM FIXTURES.
- $\langle \overline{17} \rangle$ remove metal bars from windows.
- 20 REMOVE WALL.
- $\langle 21 \rangle$ REMOVE DOOR.
- (24) REMOVE COUNTERTOPS.
- 26 REMOVE LIGHT FIXTURE.
- 27) DEMOLISH GARAGE.

- $\langle 2 \rangle$ remove porch railings and stair handrails.
- $\langle 3 \rangle$ remove and salvage stone steps.
- $\langle 5 \rangle$ remove mesh screen and salvage frame.
- $\langle 6 \rangle$ dismantle piers, including concrete bases. SALVAGE BRICK.
- 7 DISMANTLE STAIR WALLS. SALVAGE BRICK AND DISPOSE
- DEMOLISH CONCRETE INFILL. TAKE CARE NOT TO DAMAGE ORIGINAL SURROUNDING MASONRY AND
- $\langle 1 1 \rangle$ install temporary shoring at porch roof and

- $\langle \overline{14} \rangle$ remove all existing toilet room partitions and STALL DOORS.
- REMOVE WALLS AND CONCRETE AT GRADE. SEE STRUCTURAL DRAWINGS FOR EXTENT BELOW GRADE.
- (18) REMOVE WINDOW INFILL PANELS.
- (19) SALVAGE WINDOW GLAZING AND FRAME, RETURN TO OWNER. SELECTIVELY REMOVE PORTION OF EXTERIOR WALL NECESSARY TO RECEIVE DOOR.
- (22) REMOVE RADIATOR.
- 23) REMOVE KITCHEN APPLIANCES AND SINK.
- 25 REMOVE CEILING TILES.

HoH

LOWER LEVEL DEMOLITION PLAN

30% REVIEW SET A100



 $\sum_{\Gamma} C$

 $\mathcal{O}_{^{\square}}$

ONALD

 C_{O}^{O}

- \bigcirc REMOVE AND SALVAGE LIGHT POSTS.
- $\overline{\langle 2 \rangle}$ remove porch railings and stair handrails.
- 3 REMOVE AND SALVAGE STONE STEPS.
- $\overline{\langle 4 \rangle}$ remove quarry tiles, salvage where possible.
- $\overline{\langle 5 \rangle}$ remove mesh screen and salvage frame.
- (6) DISMANTLE PIERS, INCLUDING CONCRETE BASES. SALVAGE BRICK.
- 7 DISMANTLE STAIR WALLS. SALVAGE BRICK AND DISPOSE OF CAST STONE CAPS. CONCRETE FOUNDATION AND BASE TO REMAIN.
- 8 DEMOLISH SIDEWALK (CITY SIDEWALK TO REMAIN).
- PREMOVE BRICK INFILL IN PORCH OPENINGS AND DEMOLISH CONCRETE INFILL. TAKE CARE NOT TO DAMAGE ORIGINAL SURROUNDING MASONRY AND CONCRETE.
- DEMOLISH WALL AND NOTIFY ARCHITECT. ARCHITECT TO INSPECT AREA BENEATH STAIRS BEFORE INFILLED.
- 11) INSTALL TEMPORARY SHORING AT PORCH ROOF AND DEMOLISH COLUMNS. SALVAGE CAST STONE BASES FOR REINSTALLATION.
- REMOVE CAST STONE AT PORCH EDGE. REMOVE AND SALVAGE STONE BENEATH FOR REINSTALLATION.
- (13) SALVAGE DOOR FOR REINSTALLATION.
- REMOVE ALL EXISTING TOILET ROOM PARTITIONS AND STALL DOORS.
- 15 REMOVE TOILET ROOM FIXTURES.
- REMOVE WALLS AND CONCRETE AT GRADE. SEE STRUCTURAL DRAWINGS FOR EXTENT BELOW GRADE.
- $\langle \overline{17} \rangle$ remove metal bars from windows.
- 18 REMOVE WINDOW INFILL PANELS.
- SALVAGE WINDOW GLAZING AND FRAME, RETURN TO OWNER. SELECTIVELY REMOVE PORTION OF EXTERIOR WALL NECESSARY TO RECEIVE DOOR.
- 20 REMOVE WALL.
- $\langle 21 \rangle$ REMOVE DOOR.
- 22 REMOVE RADIATOR.
- 23 REMOVE KITCHEN APPLIANCES AND SINK.
- 24) REMOVE COUNTERTOPS.
- 25 REMOVE CEILING TILES.
- 26) REMOVE LIGHT FIXTURE.
- 27 DEMOLISH GARAGE.

arles Thompson Memorial Hall bilitation, HVAC Upgrade, and Addition

 $\varphi_{^{\sqcap}}$

ONALD

MACDO

A R C

4 00 SOUTH FOURTH ST

P 6 12 341 4051

Rehabilitation, HVAC Upgrao

FIRST FLOOR DEMOLITION PLAN

30% REVIEW SET

A102 1/4" = 1'-0"

REMOVAL NOTES

- 7 DISMANTLE STAIR WALLS. SALVAGE BRICK AND DISPOSE BASE TO REMAIN.
- 8 DEMOLISH SIDEWALK (CITY SIDEWALK TO REMAIN).
- 10 DEMOLISH WALL AND NOTIFY ARCHITECT. ARCHITECT TO INSPECT AREA BENEATH STAIRS BEFORE INFILLED.
- DEMOLISH COLUMNS. SALVAGE CAST STONE BASES FOR REINSTALLATION.
- 12) REMOVE CAST STONE AT PORCH EDGE. REMOVE AND SALVAGE STONE BENEATH FOR REINSTALLATION.
- (13) SALVAGE DOOR FOR REINSTALLATION.
- STALL DOORS.
- 16) remove walls and concrete at grade. See
- 17 REMOVE METAL BARS FROM WINDOWS.
- (18) REMOVE WINDOW INFILL PANELS.
- (19) SALVAGE WINDOW GLAZING AND FRAME, RETURN TO OWNER. SELECTIVELY REMOVE PORTION OF EXTERIOR WALL NECESSARY TO RECEIVE DOOR.
- 20 REMOVE WALL.
- $\langle \overline{21} \rangle$ REMOVE DOOR.
- 23 REMOVE KITCHEN APPLIANCES AND SINK.
- 24) REMOVE COUNTERTOPS.
- (25) REMOVE CEILING TILES.
- 26) REMOVE LIGHT FIXTURE.
- 27) DEMOLISH GARAGE.



- $\fbox{1}$ remove and salvage light posts.
- $\langle 2 \rangle$ remove porch railings and stair handrails.
- 3 REMOVE AND SALVAGE STONE STEPS.
- 4 REMOVE QUARRY TILES, SALVAGE WHERE POSSIBLE.
- (5) REMOVE MESH SCREEN AND SALVAGE FRAME.
- (6) DISMANTLE PIERS, INCLUDING CONCRETE BASES. SALVAGE BRICK.
- OF CAST STONE CAPS. CONCRETE FOUNDATION AND
- 9 REMOVE BRICK INFILL IN PORCH OPENINGS AND DEMOLISH CONCRETE INFILL. TAKE CARE NOT TO DAMAGE ORIGINAL SURROUNDING MASONRY AND CONCRETE.
- $\langle 11 \rangle$ install temporary shoring at porch roof and

- 14) REMOVE ALL EXISTING TOILET ROOM PARTITIONS AND
- (15) REMOVE TOILET ROOM FIXTURES.
- STRUCTURAL DRAWINGS FOR EXTENT BELOW GRADE.

- 22 REMOVE RADIATOR.


Thompson Memorial Hall In, HVAC Upgrade, and Addition

SECOND FLOOR DEMOLITION

PLAN

30% REVIEW SET

A102



ONALD MACD


A R C

4 00 SOUTH FOURTH ST

P 612 341 4051


1 A302

- \bigcirc REMOVE AND SALVAGE LIGHT POSTS.
- $\langle 2 \rangle$ remove porch railings and stair handrails.
- 3 REMOVE AND SALVAGE STONE STEPS.
- $\overline{\langle 4 \rangle}$ remove quarry tiles, salvage where possible.
- $\langle 5 \rangle$ remove mesh screen and salvage frame.
- (6) DISMANTLE PIERS, INCLUDING CONCRETE BASES. SALVAGE BRICK.
- 7 DISMANTLE STAIR WALLS. SALVAGE BRICK AND DISPOSE OF CAST STONE CAPS. CONCRETE FOUNDATION AND BASE TO REMAIN.
- 8 DEMOLISH SIDEWALK (CITY SIDEWALK TO REMAIN).
- 9 REMOVE BRICK INFILL IN PORCH OPENINGS AND DEMOLISH CONCRETE INFILL. TAKE CARE NOT TO DAMAGE ORIGINAL SURROUNDING MASONRY AND CONCRETE.
- 10 DEMOLISH WALL AND NOTIFY ARCHITECT. ARCHITECT TO INSPECT AREA BENEATH STAIRS BEFORE INFILLED.
- (11) INSTALL TEMPORARY SHORING AT PORCH ROOF AND DEMOLISH COLUMNS. SALVAGE CAST STONE BASES FOR REINSTALLATION.
- 12) REMOVE CAST STONE AT PORCH EDGE. REMOVE AND SALVAGE STONE BENEATH FOR REINSTALLATION.
- (13) SALVAGE DOOR FOR REINSTALLATION.
- 14) REMOVE ALL EXISTING TOILET ROOM PARTITIONS AND STALL DOORS.
- (15) REMOVE TOILET ROOM FIXTURES.
- REMOVE WALLS AND CONCRETE AT GRADE. SEE STRUCTURAL DRAWINGS FOR EXTENT BELOW GRADE.
- (17) REMOVE METAL BARS FROM WINDOWS.
- 18 REMOVE WINDOW INFILL PANELS.
- (19) SALVAGE WINDOW GLAZING AND FRAME, RETURN TO OWNER. SELECTIVELY REMOVE PORTION OF EXTERIOR WALL NECESSARY TO RECEIVE DOOR.
- 20 REMOVE WALL.
- $\langle 21 \rangle$ REMOVE DOOR.
- 22 REMOVE RADIATOR.
- 23 REMOVE KITCHEN APPLIANCES AND SINK.
- 24) REMOVE COUNTERTOPS.
- $\langle \overline{25} \rangle$ remove ceiling tiles.
- 26) REMOVE LIGHT FIXTURE.
- 27) DEMOLISH GARAGE.



 $\sum_{\mathbf{A}} \mathbf{A}$ $\mathcal{O}_{^{\square}}$

ONALD A R C
4 0 0 SOUTH FOURTH ST
P 6 1 2 3 4 1 4 0 5 1 . . .





THIRD FLOOR DEMOLITION PLAN

30% REVIEW SET A103

1 ROOF DEMOLITION PLAN


REMOVAL NOTES

- \bigcirc Remove and Salvage light posts.
- $\langle 2 \rangle$ remove porch railings and stair handrails.
- (3) REMOVE AND SALVAGE STONE STEPS.
- 4 REMOVE QUARRY TILES, SALVAGE WHERE POSSIBLE.
- $\langle 5 \rangle$ remove mesh screen and salvage frame.
- (6) DISMANTLE PIERS, INCLUDING CONCRETE BASES. SALVAGE BRICK.
- DISMANTLE STAIR WALLS. SALVAGE BRICK AND DISPOSE OF CAST STONE CAPS. CONCRETE FOUNDATION AND BASE TO REMAIN.
- 8 DEMOLISH SIDEWALK (CITY SIDEWALK TO REMAIN).
- PREMOVE BRICK INFILL IN PORCH OPENINGS AND DEMOLISH CONCRETE INFILL. TAKE CARE NOT TO DAMAGE ORIGINAL SURROUNDING MASONRY AND CONCRETE.
- DEMOLISH WALL AND NOTIFY ARCHITECT. ARCHITECT TO INSPECT AREA BENEATH STAIRS BEFORE INFILLED.
- 11) INSTALL TEMPORARY SHORING AT PORCH ROOF AND DEMOLISH COLUMNS. SALVAGE CAST STONE BASES FOR REINSTALLATION.
- (12) REMOVE CAST STONE AT PORCH EDGE. REMOVE AND SALVAGE STONE BENEATH FOR REINSTALLATION.
- (13) SALVAGE DOOR FOR REINSTALLATION.
- REMOVE ALL EXISTING TOILET ROOM PARTITIONS AND STALL DOORS.
- (15) REMOVE TOILET ROOM FIXTURES.
- REMOVE WALLS AND CONCRETE AT GRADE. SEE STRUCTURAL DRAWINGS FOR EXTENT BELOW GRADE.
- $\langle \overline{17} \rangle$ remove metal bars from windows.
- 18 REMOVE WINDOW INFILL PANELS.
- SALVAGE WINDOW GLAZING AND FRAME, RETURN TO OWNER. SELECTIVELY REMOVE PORTION OF EXTERIOR WALL NECESSARY TO RECEIVE DOOR.
- 20 REMOVE WALL.
- $\langle \overline{21} \rangle$ remove door.
- 22 remove radiator.
- 23 REMOVE KITCHEN APPLIANCES AND SINK.
- 24) REMOVE COUNTERTOPS.
- 25 REMOVE CEILING TILES.
- 26 REMOVE LIGHT FIXTURE.
- 27) DEMOLISH GARAGE.



A R C T
4 0 0 SOUTH FOURTH STREET STE
P 612 341 4051 • F 612 3

I hearby certify that this plan, specification, or report of the State of Minnesota





ROOF DEMOLITION

PLAN

A104

30% REVIEW SET



SALVAGE BRICK.

- 1 REMOVE AND SALVAGE LIGHT POSTS.
- $\langle 2 \rangle$ remove porch railings and stair handrails.
- 3 REMOVE AND SALVAGE STONE STEPS.
- $\overline{\langle 4 \rangle}$ remove quarry tiles, salvage where possible.
- $\langle 5 \rangle$ remove mesh screen and salvage frame.
- (6) DISMANTLE PIERS, INCLUDING CONCRETE BASES.
- DISMANTLE STAIR WALLS. SALVAGE BRICK AND DISPOSE OF CAST STONE CAPS. CONCRETE FOUNDATION AND BASE TO REMAIN.
- 8 DEMOLISH SIDEWALK (CITY SIDEWALK TO REMAIN).
- PREMOVE BRICK INFILL IN PORCH OPENINGS AND DEMOLISH CONCRETE INFILL. TAKE CARE NOT TO DAMAGE ORIGINAL SURROUNDING MASONRY AND CONCRETE.
- DEMOLISH WALL AND NOTIFY ARCHITECT. ARCHITECT TO INSPECT AREA BENEATH STAIRS BEFORE INFILLED.
- 11) INSTALL TEMPORARY SHORING AT PORCH ROOF AND DEMOLISH COLUMNS. SALVAGE CAST STONE BASES FOR REINSTALLATION.
- (12) REMOVE CAST STONE AT PORCH EDGE. REMOVE AND SALVAGE STONE BENEATH FOR REINSTALLATION.
- $\langle 13 \rangle$ Salvage door for reinstallation.
- REMOVE ALL EXISTING TOILET ROOM PARTITIONS AND STALL DOORS.
- (15) REMOVE TOILET ROOM FIXTURES.
- (16) REMOVE WALLS AND CONCRETE AT GRADE. SEE STRUCTURAL DRAWINGS FOR EXTENT BELOW GRADE.
- $\langle \overline{17} \rangle$ remove metal bars from windows.
- 18 REMOVE WINDOW INFILL PANELS.
- SALVAGE WINDOW GLAZING AND FRAME, RETURN TO OWNER. SELECTIVELY REMOVE PORTION OF EXTERIOR WALL NECESSARY TO RECEIVE DOOR.
- 20 REMOVE WALL.
- $\langle \overline{21} \rangle$ remove door.
- 22 REMOVE RADIATOR.
- 23 REMOVE KITCHEN APPLIANCES AND SINK.
- 24) REMOVE COUNTERTOPS.
- 25 REMOVE CEILING TILES.
- 26 REMOVE LIGHT FIXTURE.
- 27) DEMOLISH GARAGE.

harles Thompson Memorial Hall

 $\sum_{\Gamma} C$

 $\varphi_{^{\sqcap}}$

ONALD

MACDO A R C 4 00 SOUTH FOURTH ST P 612 341 4051

RCP LOWER LEVEL
DEMOLITION

A105

30% REVIEW SET



removal notes


- 1 REMOVE AND SALVAGE LIGHT POSTS.
- $\langle 2 \rangle$ remove porch railings and stair handrails.
- $\langle 3 \rangle$ remove and salvage stone steps.
- $\overline{\langle 4 \rangle}$ remove quarry tiles, salvage where possible.
- $\langle 5 \rangle$ remove mesh screen and salvage frame.
- 6 DISMANTLE PIERS, INCLUDING CONCRETE BASES. SALVAGE BRICK.
- 7 DISMANTLE STAIR WALLS. SALVAGE BRICK AND DISPOSE OF CAST STONE CAPS. CONCRETE FOUNDATION AND BASE TO REMAIN.
- 8 DEMOLISH SIDEWALK (CITY SIDEWALK TO REMAIN).
- PREMOVE BRICK INFILL IN PORCH OPENINGS AND DEMOLISH CONCRETE INFILL. TAKE CARE NOT TO DAMAGE ORIGINAL SURROUNDING MASONRY AND CONCRETE.
- DEMOLISH WALL AND NOTIFY ARCHITECT. ARCHITECT TO INSPECT AREA BENEATH STAIRS BEFORE INFILLED.
- 11) INSTALL TEMPORARY SHORING AT PORCH ROOF AND DEMOLISH COLUMNS. SALVAGE CAST STONE BASES FOR REINSTALLATION.
- REMOVE CAST STONE AT PORCH EDGE. REMOVE AND SALVAGE STONE BENEATH FOR REINSTALLATION.
- $\langle 13 \rangle$ Salvage door for reinstallation.
- REMOVE ALL EXISTING TOILET ROOM PARTITIONS AND STALL DOORS.
- (15) REMOVE TOILET ROOM FIXTURES.
- REMOVE WALLS AND CONCRETE AT GRADE. SEE STRUCTURAL DRAWINGS FOR EXTENT BELOW GRADE.
- (17) REMOVE METAL BARS FROM WINDOWS.
- (18) REMOVE WINDOW INFILL PANELS.
- SALVAGE WINDOW GLAZING AND FRAME, RETURN TO OWNER. SELECTIVELY REMOVE PORTION OF EXTERIOR WALL NECESSARY TO RECEIVE DOOR.
- 20 REMOVE WALL.
- $\langle \overline{21} \rangle$ remove door.
- 22 remove radiator.
- 23 REMOVE KITCHEN APPLIANCES AND SINK.

30% REVIEW SET

- 24) REMOVE COUNTERTOPS.
- 25 REMOVE CEILING TILES.
- 26 REMOVE LIGHT FIXTURE.
- 27) DEMOLISH GARAGE.



A R C H I TREET STE 7 1 2 MIN P 612 341 4051 . F 612 337 5843





RCP FIRST FLOOR DEMOLITION

A107 1/4" = 1'-0"

REMOVAL NOTES

- (6) DISMANTLE PIERS, INCLUDING CONCRETE BASES.
- OF CAST STONE CAPS. CONCRETE FOUNDATION AND BASE TO REMAIN.
- 8 DEMOLISH SIDEWALK (CITY SIDEWALK TO REMAIN).
- $\overline{\langle 9 \rangle}$ remove brick infill in Porch openings and DEMOLISH CONCRETE INFILL. TAKE CARE NOT TO CONCRETE.
- 10 DEMOLISH WALL AND NOTIFY ARCHITECT. ARCHITECT TO INSPECT AREA BENEATH STAIRS BEFORE INFILLED.
- (11) INSTALL TEMPORARY SHORING AT PORCH ROOF AND DEMOLISH COLUMNS. SALVAGE CAST STONE BASES FOR REINSTALLATION.
- SALVAGE STONE BENEATH FOR REINSTALLATION.
- $\langle 13 \rangle$ Salvage door for reinstallation.
- 14) REMOVE ALL EXISTING TOILET ROOM PARTITIONS AND STALL DOORS.
- (15) REMOVE TOILET ROOM FIXTURES.
- 18 REMOVE WINDOW INFILL PANELS.
- (19) SALVAGE WINDOW GLAZING AND FRAME, RETURN TO OWNER. SELECTIVELY REMOVE PORTION OF EXTERIOR WALL NECESSARY TO RECEIVE DOOR.
- 20 REMOVE WALL.
- $\langle 21 \rangle$ REMOVE DOOR.
- 22 REMOVE RADIATOR.
- 23 REMOVE KITCHEN APPLIANCES AND SINK.
- 24) REMOVE COUNTERTOPS.
- 27) DEMOLISH GARAGE.



- \bigcirc REMOVE AND SALVAGE LIGHT POSTS.
- $\langle 2 \rangle$ remove porch railings and stair handrails.
- 3 REMOVE AND SALVAGE STONE STEPS.
- $\overline{\langle 4 \rangle}$ remove quarry tiles, salvage where possible.
- (5) REMOVE MESH SCREEN AND SALVAGE FRAME.
- SALVAGE BRICK.
- 7 DISMANTLE STAIR WALLS. SALVAGE BRICK AND DISPOSE
- DAMAGE ORIGINAL SURROUNDING MASONRY AND
- 12) REMOVE CAST STONE AT PORCH EDGE. REMOVE AND

- 16) remove walls and concrete at grade. See STRUCTURAL DRAWINGS FOR EXTENT BELOW GRADE.
- $\langle \overline{17} \rangle$ remove metal bars from windows.

- (25) REMOVE CEILING TILES.
- 26) REMOVE LIGHT FIXTURE.



 $\wp_{\scriptscriptstyle \Pi}$

ONALD

A R C
4 0 0 SOUTH FOURTH ST
P 6 1 2 3 4 1 4 0 5 1 . . .

RCP SECOND FLOOR

A107

DEMOLITION



REMOVAL NOTES

- (6) DISMANTLE PIERS, INCLUDING CONCRETE BASES.
- 7 DISMANTLE STAIR WALLS. SALVAGE BRICK AND DISPOSE OF CAST STONE CAPS. CONCRETE FOUNDATION AND BASE TO REMAIN.
- FOR REINSTALLATION.
- $\langle 13 \rangle$ Salvage door for reinstallation.
- STALL DOORS.
- STRUCTURAL DRAWINGS FOR EXTENT BELOW GRADE.
- 18 REMOVE WINDOW INFILL PANELS.
- 20 REMOVE WALL.
- $\langle 21 \rangle$ REMOVE DOOR.
- 22 REMOVE RADIATOR.
- 23 REMOVE KITCHEN APPLIANCES AND SINK.

30% REVIEW SET

- 24) REMOVE COUNTERTOPS.
- (25) REMOVE CEILING TILES.
- 26) REMOVE LIGHT FIXTURE.
- 27) DEMOLISH GARAGE.



- \bigcirc REMOVE AND SALVAGE LIGHT POSTS.
- $\langle 2 \rangle$ remove porch railings and stair handrails.
- 3 REMOVE AND SALVAGE STONE STEPS.
- 4 REMOVE QUARRY TILES, SALVAGE WHERE POSSIBLE.
- $\langle 5 \rangle$ remove mesh screen and salvage frame.
- SALVAGE BRICK.
- 8 DEMOLISH SIDEWALK (CITY SIDEWALK TO REMAIN).
- $\langle 9 \rangle$ remove brick infill in Porch openings and DEMOLISH CONCRETE INFILL. TAKE CARE NOT TO DAMAGE ORIGINAL SURROUNDING MASONRY AND CONCRETE.
- 10 DEMOLISH WALL AND NOTIFY ARCHITECT. ARCHITECT TO INSPECT AREA BENEATH STAIRS BEFORE INFILLED.
- (11) INSTALL TEMPORARY SHORING AT PORCH ROOF AND DEMOLISH COLUMNS. SALVAGE CAST STONE BASES
- 12) REMOVE CAST STONE AT PORCH EDGE. REMOVE AND SALVAGE STONE BENEATH FOR REINSTALLATION.
- 14) REMOVE ALL EXISTING TOILET ROOM PARTITIONS AND
- (15) REMOVE TOILET ROOM FIXTURES.
- REMOVE WALLS AND CONCRETE AT GRADE. SEE
- $\langle \overline{17} \rangle$ remove metal bars from windows.
- (19) SALVAGE WINDOW GLAZING AND FRAME, RETURN TO OWNER. SELECTIVELY REMOVE PORTION OF EXTERIOR WALL NECESSARY TO RECEIVE DOOR.

Charles Thompson Memorial Hall Rehabilitation, HVAC Upgrade, and Addition

RCP THIRD FLOOR

A108

DEMOLITION



ONALD

A R C
4 0 0 SOUTH FOURTH ST
P 6 1 2 3 4 1 4 0 5 1 . . .

(1) POUR CONCRETE FOOTINGS AND PIER BASE.

CONSTRUCTION NOTES

- 2 RESET STONE AT PORCH EDGE AND INSTALL

 \mathbf{A}

 \mathcal{P}_{\square}

ONALD

HoH

Memorial F

Thompson Moon, HVAC Upgrade, a

Charles The Rehabilitation, I

- MATCHING REPLACEMENT BRICK WHERE NECESSARY. INSTALL REPLACEMENT CAST STONE CAPS TO MATCH ORIGINAL.
- PORCH. PAINT (DO NOT PAINT STEPS).
- (6) REINSTALL STEPS.
- (8) INSTALL FLEXIBLE JOINT.
- 9 CONSTRUCT NEW WALL AND INFILL AREA BENEATH STAIRS. SEE STRUCTURAL.
- (10) INSTALL BALUSTRADE AND GUARDRAILS AT PORCH AND STEPS. INSTALL HANDRAILS AT STEPS.
- (12) REPAIR AND PAINT SALVAGED WOOD FRAME AND INSTALL NEW PANEL IN PLACE OF MESH. REINSTALL.
- INSIDE OF FRIEZE, AND ARCHITRAVE, WITH CONSOLIDANT. PAINT.
- (14) REPAIR AND EXTEND DOWNSPOUTS TO PROVIDE PIECES THAT ARE REUSED.
- THRESHOLD.
- SEE DOOR SCHEDULE ON A601 FOR HARDWARE.
- (17) INSTALL PERMANENT DOOR STOP.
- (18) INSTALL LIGHT. SEE SCHEDULE.
- (20) REGRADE DISTURBED AREA AROUND BOTTOM OF STAIRS AND PIERS, REPLACE SOD.
- (21) INFILL OPENINGS WITH CONCRETE MASONRY UNITS.
- WATERPROOF EXTERIOR OF BUILDING BELOW GRADE AND INFILL WHERE CONCRETE WAS REMOVED. SEE
- (23) TOILET FIXTURE. SEE SCHEDULE.
- (24) URINAL. SEE SCHEDULE.
- (25) SINK AND FAUCET. SEE SCHEDULE.
- (27) TOILET ROOM PARTITIONS AND DOORS.
- (28) CONSTRUCT WALL.
- (29) DOOR. SEE SCHEDULE.
- (30) WINDOW. SEE SCHEDULE.
- (31) REINSTALL SALVAGED QUARRY TILE AND INSTALL NEW TILE WHERE NECESSARY.
- (32) PAINT METAL CORNICE AND PARAPET CAP.
- (33) REPAIR DAMAGE TO CONCRETE FROM PIPES AND CONDUIT. SEAL OPENING IN MASONRY AROUND
- (34) PAINT WOOD TRIM AND CORNICE OF BOW WINDOW
- (35) PAINT WOOD ON EXTERIOR SIDE OF EXISTING WINDOW/DOOR.
- (36) REPAIR WOOD AT BOTTOM OF CORNICE.

- REPLACEMENT CAST STONE TO MATCH ORIGINAL. (3) INSTALL DORIC COLUMNS AND REINSTALL SALVAGED
- (4) REBUILD STAIR WALLS USING SALVAGED BRICK AND
- (5) REPLACE CAST STONE AT STAIRS AND TOP BAND AT
- (7) RECONSTRUCT CONCRETE WALK.

- (11) INSTALL PANELS AT PORCH OPENINGS.
- (13) REPAIR WOOD ENTABLATURE, INCLUDING CORNICE,
- DRAINAGE AWAY FROM THE BUILDING. PAINT EXISTING
- (15) CLEAN CAST STONE AROUND DOOR AND
- (16) REPAIR DOORS AND PAINT, INCLUDING WOOD TRIM.
- (19) RESTORE AND REINSTALL LAMPS. PAINT METAL AND PROVIDE NEW GLOBES.

- STRUCTURAL FOR EXTENT AND FILL REQUIREMENTS. SEE CIVIL FOR REGRADING.

- (26) TOILET ROOM EQUIPMENT. SEE ELEVATIONS AND SCHEDULE.

- (37) MODIFY THRESHOLD AND SEAL JOINTS.

A200

LOWER LEVEL

PLAN

CONSTRUCTION




A200 1/4" = 1'-0"

A201 1/4" = 1'-0"

CONSTRUCTION NOTES

- (1) POUR CONCRETE FOOTINGS AND PIER BASE.
- 2 RESET STONE AT PORCH EDGE AND INSTALL REPLACEMENT CAST STONE TO MATCH ORIGINAL.
- 3 INSTALL DORIC COLUMNS AND REINSTALL SALVAGED BASES
- 4 REBUILD STAIR WALLS USING SALVAGED BRICK AND MATCHING REPLACEMENT BRICK WHERE NECESSARY. INSTALL REPLACEMENT CAST STONE CAPS TO MATCH ORIGINAL.
- 5 REPLACE CAST STONE AT STAIRS AND TOP BAND AT PORCH. PAINT (DO NOT PAINT STEPS).
- (6) REINSTALL STEPS.
- (7) RECONSTRUCT CONCRETE WALK.
- (8) INSTALL FLEXIBLE JOINT.
- 9 CONSTRUCT NEW WALL AND INFILL AREA BENEATH STAIRS. SEE STRUCTURAL.
- 10 INSTALL BALUSTRADE AND GUARDRAILS AT PORCH AND STEPS. INSTALL HANDRAILS AT STEPS.
- (11) INSTALL PANELS AT PORCH OPENINGS.
- REPAIR AND PAINT SALVAGED WOOD FRAME AND INSTALL NEW PANEL IN PLACE OF MESH. REINSTALL.
- 13) REPAIR WOOD ENTABLATURE, INCLUDING CORNICE, INSIDE OF FRIEZE, AND ARCHITRAVE, WITH CONSOLIDANT. PAINT.
- REPAIR AND EXTEND DOWNSPOUTS TO PROVIDE DRAINAGE AWAY FROM THE BUILDING. PAINT EXISTING PIECES THAT ARE REUSED.
- (15) CLEAN CAST STONE AROUND DOOR AND THRESHOLD.
- (16) REPAIR DOORS AND PAINT, INCLUDING WOOD TRIM. SEE DOOR SCHEDULE ON A601 FOR HARDWARE.
- (17) INSTALL PERMANENT DOOR STOP.
- (18) INSTALL LIGHT. SEE SCHEDULE.
- (19) RESTORE AND REINSTALL LAMPS. PAINT METAL AND PROVIDE NEW GLOBES.
- 20 REGRADE DISTURBED AREA AROUND BOTTOM OF STAIRS AND PIERS, REPLACE SOD.
- (21) INFILL OPENINGS WITH CONCRETE MASONRY UNITS.
- WATERPROOF EXTERIOR OF BUILDING BELOW GRADE AND INFILL WHERE CONCRETE WAS REMOVED. SEE STRUCTURAL FOR EXTENT AND FILL REQUIREMENTS. SEE CIVIL FOR REGRADING.
- 23) TOILET FIXTURE. SEE SCHEDULE.
- 24) URINAL. SEE SCHEDULE.
- 25) SINK AND FAUCET. SEE SCHEDULE.
- (26) TOILET ROOM EQUIPMENT. SEE ELEVATIONS AND SCHEDULE.
- (27) TOILET ROOM PARTITIONS AND DOORS.
- (28) CONSTRUCT WALL.
- (29) DOOR. SEE SCHEDULE.
- (30) WINDOW. SEE SCHEDULE.
- (31) REINSTALL SALVAGED QUARRY TILE AND INSTALL NEW TILE WHERE NECESSARY.
- (32) PAINT METAL CORNICE AND PARAPET CAP.
- (33) REPAIR DAMAGE TO CONCRETE FROM PIPES AND CONDUIT. SEAL OPENING IN MASONRY AROUND PIPES.
- (34) PAINT WOOD TRIM AND CORNICE OF BOW WINDOW EXTERIOR.
- (35) PAINT WOOD ON EXTERIOR SIDE OF EXISTING WINDOW/DOOR.
- (36) REPAIR WOOD AT BOTTOM OF CORNICE.
- 37 modify threshold and seal joints.



ONALD & MACK

H I T E C T S

STREET STE 7 1.2 MINNEAPOLIS MINNES OTA 5 5 4 1 5

4 0 0 SOUTH FOURTH STREETSTE 7
P 612 341 4051 • F 612 337
I hearby certify that this plan, specification, or report was

Z

Charles Thompson Memorial Henabilitation, HVAC Upgrade, and Addition

HaH

1824 M

FIRST FLOOR

CONSTRUCTION

PLAN

- (1) POUR CONCRETE FOOTINGS AND PIER BASE.
- REPLACEMENT CAST STONE TO MATCH ORIGINAL.
- MATCHING REPLACEMENT BRICK WHERE NECESSARY. INSTALL REPLACEMENT CAST STONE CAPS TO MATCH ORIGINAL.
- PORCH. PAINT (DO NOT PAINT STEPS).
- (6) REINSTALL STEPS.
- (9) CONSTRUCT NEW WALL AND INFILL AREA BENEATH STAIRS. SEE STRUCTURAL.
- (10) INSTALL BALUSTRADE AND GUARDRAILS AT PORCH AND STEPS. INSTALL HANDRAILS AT STEPS.
- (11) INSTALL PANELS AT PORCH OPENINGS.
- (13) REPAIR WOOD ENTABLATURE, INCLUDING CORNICE, INSIDE OF FRIEZE, AND ARCHITRAVE, WITH CONSOLIDANT. PAINT.
- (14) REPAIR AND EXTEND DOWNSPOUTS TO PROVIDE DRAINAGE AWAY FROM THE BUILDING. PAINT EXISTING
- (17) INSTALL PERMANENT DOOR STOP.
- (18) INSTALL LIGHT. SEE SCHEDULE.
- PROVIDE NEW GLOBES.
- (21) INFILL OPENINGS WITH CONCRETE MASONRY UNITS.
- (22) WATERPROOF EXTERIOR OF BUILDING BELOW GRADE AND INFILL WHERE CONCRETE WAS REMOVED. SEE
- (23) TOILET FIXTURE. SEE SCHEDULE.
- (25) SINK AND FAUCET. SEE SCHEDULE.
- (26) TOILET ROOM EQUIPMENT. SEE ELEVATIONS AND
- (27) TOILET ROOM PARTITIONS AND DOORS.
- (28) CONSTRUCT WALL.
- 29) DOOR. SEE SCHEDULE.
- (30) WINDOW. SEE SCHEDULE.
- (31) REINSTALL SALVAGED QUARRY TILE AND INSTALL NEW TILE WHERE NECESSARY.
- (32) PAINT METAL CORNICE AND PARAPET CAP.
- (33) REPAIR DAMAGE TO CONCRETE FROM PIPES AND CONDUIT. SEAL OPENING IN MASONRY AROUND
- (34) PAINT WOOD TRIM AND CORNICE OF BOW WINDOW
- (36) REPAIR WOOD AT BOTTOM OF CORNICE.
- (37) MODIFY THRESHOLD AND SEAL JOINTS.

CONSTRUCTION NOTES





(3) INSTALL DORIC COLUMNS AND REINSTALL SALVAGED

- (4) REBUILD STAIR WALLS USING SALVAGED BRICK AND
- 5 REPLACE CAST STONE AT STAIRS AND TOP BAND AT
- (7) RECONSTRUCT CONCRETE WALK.
- (8) INSTALL FLEXIBLE JOINT.

- (12) REPAIR AND PAINT SALVAGED WOOD FRAME AND INSTALL NEW PANEL IN PLACE OF MESH. REINSTALL.
- PIECES THAT ARE REUSED.
- (15) CLEAN CAST STONE AROUND DOOR AND THRESHOLD.
- (16) REPAIR DOORS AND PAINT, INCLUDING WOOD TRIM. SEE DOOR SCHEDULE ON A601 FOR HARDWARE.


- (19) RESTORE AND REINSTALL LAMPS. PAINT METAL AND
- (20) REGRADE DISTURBED AREA AROUND BOTTOM OF STAIRS AND PIERS, REPLACE SOD.
- STRUCTURAL FOR EXTENT AND FILL REQUIREMENTS. SEE CIVIL FOR REGRADING.
- (24) URINAL. SEE SCHEDULE.

- (35) PAINT WOOD ON EXTERIOR SIDE OF EXISTING WINDOW/DOOR.

A202

O N S \mathbf{A}

 $\mathcal{O}_{^{\square}}$ ONALD



HaH

Memorial H

Thompson Moon, HVAC Upgrade, a

SECOND FLOOR CONSTRUCTION PLAN

1 | SECOND FLOOR CONSTRUCTION PLAN A202 | 1/4" = 1'-0"

- (1) POUR CONCRETE FOOTINGS AND PIER BASE.
- (3) INSTALL DORIC COLUMNS AND REINSTALL SALVAGED
- (4) REBUILD STAIR WALLS USING SALVAGED BRICK AND ORIGINAL.

- 9 CONSTRUCT NEW WALL AND INFILL AREA BENEATH STAIRS. SEE STRUCTURAL.
- (10) INSTALL BALUSTRADE AND GUARDRAILS AT PORCH AND STEPS. INSTALL HANDRAILS AT STEPS.
- (11) INSTALL PANELS AT PORCH OPENINGS.
- INSIDE OF FRIEZE, AND ARCHITRAVE, WITH CONSOLIDANT. PAINT.
- (14) REPAIR AND EXTEND DOWNSPOUTS TO PROVIDE DRAINAGE AWAY FROM THE BUILDING. PAINT EXISTING
- (17) INSTALL PERMANENT DOOR STOP.
- (18) INSTALL LIGHT. SEE SCHEDULE.
- STAIRS AND PIERS, REPLACE SOD.
- (21) INFILL OPENINGS WITH CONCRETE MASONRY UNITS.
- (22) WATERPROOF EXTERIOR OF BUILDING BELOW GRADE AND INFILL WHERE CONCRETE WAS REMOVED. SEE
- (23) TOILET FIXTURE. SEE SCHEDULE.
- (24) URINAL. SEE SCHEDULE.
- (25) SINK AND FAUCET. SEE SCHEDULE.
- SCHEDULE.
- (27) TOILET ROOM PARTITIONS AND DOORS.
- (29) DOOR. SEE SCHEDULE.
- (30) WINDOW. SEE SCHEDULE.
- (31) REINSTALL SALVAGED QUARRY TILE AND INSTALL NEW TILE WHERE NECESSARY.
- (32) PAINT METAL CORNICE AND PARAPET CAP.
- (33) REPAIR DAMAGE TO CONCRETE FROM PIPES AND CONDUIT. SEAL OPENING IN MASONRY AROUND
- (34) PAINT WOOD TRIM AND CORNICE OF BOW WINDOW
- (35) PAINT WOOD ON EXTERIOR SIDE OF EXISTING
- (36) REPAIR WOOD AT BOTTOM OF CORNICE.
- (37) MODIFY THRESHOLD AND SEAL JOINTS.

30% REVIEW SET







- MATCHING REPLACEMENT BRICK WHERE NECESSARY. INSTALL REPLACEMENT CAST STONE CAPS TO MATCH
- (5) REPLACE CAST STONE AT STAIRS AND TOP BAND AT PORCH. PAINT (DO NOT PAINT STEPS).
- (6) REINSTALL STEPS.
- (7) RECONSTRUCT CONCRETE WALK.
- (8) INSTALL FLEXIBLE JOINT.
- (12) REPAIR AND PAINT SALVAGED WOOD FRAME AND INSTALL NEW PANEL IN PLACE OF MESH. REINSTALL.
- (13) REPAIR WOOD ENTABLATURE, INCLUDING CORNICE,
- PIECES THAT ARE REUSED.
- (15) CLEAN CAST STONE AROUND DOOR AND THRESHOLD.
- (16) REPAIR DOORS AND PAINT, INCLUDING WOOD TRIM. SEE DOOR SCHEDULE ON A601 FOR HARDWARE.

- (19) RESTORE AND REINSTALL LAMPS. PAINT METAL AND PROVIDE NEW GLOBES.
- (20) REGRADE DISTURBED AREA AROUND BOTTOM OF
- STRUCTURAL FOR EXTENT AND FILL REQUIREMENTS. SEE CIVIL FOR REGRADING.


- (26) TOILET ROOM EQUIPMENT. SEE ELEVATIONS AND
- (28) CONSTRUCT WALL.

- WINDOW/DOOR.
- A203

PLAN


THIRD FLOOR

CONSTRUCTION



 $\frac{1}{2}$

M C $\mathcal{O}_{^{\square}}$ ONALD



HoH

Memorial H

Thompson

A204 1/4" = 1'-0"

- MATCHING REPLACEMENT BRICK WHERE NECESSARY. INSTALL REPLACEMENT CAST STONE CAPS TO MATCH ORIGINAL.
- 5 REPLACE CAST STONE AT STAIRS AND TOP BAND AT PORCH. PAINT (DO NOT PAINT STEPS).

- (10) INSTALL BALUSTRADE AND GUARDRAILS AT PORCH AND STEPS. INSTALL HANDRAILS AT STEPS.
- (11) INSTALL PANELS AT PORCH OPENINGS.
- (13) REPAIR WOOD ENTABLATURE, INCLUDING CORNICE, INSIDE OF FRIEZE, AND ARCHITRAVE, WITH CONSOLIDANT. PAINT.
- (14) REPAIR AND EXTEND DOWNSPOUTS TO PROVIDE
- SEE DOOR SCHEDULE ON A601 FOR HARDWARE.
- (17) Install permanent door stop.
- (18) INSTALL LIGHT. SEE SCHEDULE.
- (21) INFILL OPENINGS WITH CONCRETE MASONRY UNITS.
- (22) WATERPROOF EXTERIOR OF BUILDING BELOW GRADE AND INFILL WHERE CONCRETE WAS REMOVED. SEE
- (23) TOILET FIXTURE. SEE SCHEDULE.
- (25) SINK AND FAUCET. SEE SCHEDULE.
- (27) TOILET ROOM PARTITIONS AND DOORS.
- 29) DOOR. SEE SCHEDULE.
- (31) REINSTALL SALVAGED QUARRY TILE AND INSTALL NEW TILE WHERE NECESSARY.
- (32) PAINT METAL CORNICE AND PARAPET CAP.
- (33) REPAIR DAMAGE TO CONCRETE FROM PIPES AND CONDUIT. SEAL OPENING IN MASONRY AROUND
- (34) PAINT WOOD TRIM AND CORNICE OF BOW WINDOW
- (36) REPAIR WOOD AT BOTTOM OF CORNICE.
- (37) MODIFY THRESHOLD AND SEAL JOINTS.

CONSTRUCTION NOTES









- (4) REBUILD STAIR WALLS USING SALVAGED BRICK AND
- (6) REINSTALL STEPS.
- (7) RECONSTRUCT CONCRETE WALK.
- (8) INSTALL FLEXIBLE JOINT.
- (9) CONSTRUCT NEW WALL AND INFILL AREA BENEATH STAIRS. SEE STRUCTURAL.
- (12) REPAIR AND PAINT SALVAGED WOOD FRAME AND INSTALL NEW PANEL IN PLACE OF MESH. REINSTALL.
- DRAINAGE AWAY FROM THE BUILDING. PAINT EXISTING PIECES THAT ARE REUSED.
- (15) CLEAN CAST STONE AROUND DOOR AND THRESHOLD.
- (16) REPAIR DOORS AND PAINT, INCLUDING WOOD TRIM.
- (19) RESTORE AND REINSTALL LAMPS. PAINT METAL AND PROVIDE NEW GLOBES.
- (20) REGRADE DISTURBED AREA AROUND BOTTOM OF STAIRS AND PIERS, REPLACE SOD.
- STRUCTURAL FOR EXTENT AND FILL REQUIREMENTS. SEE CIVIL FOR REGRADING.
- (24) URINAL. SEE SCHEDULE.
- (26) TOILET ROOM EQUIPMENT. SEE ELEVATIONS AND
- (28) CONSTRUCT WALL.
- (30) WINDOW. SEE SCHEDULE.

- (35) PAINT WOOD ON EXTERIOR SIDE OF EXISTING WINDOW/DOOR.

30% REVIEW SET



O L M O $\varphi_{\text{\tiny m}}$ ONALD



HaH

Memorial H

ROOF

CONSTRUCTION PLAN

- (4) REBUILD STAIR WALLS USING SALVAGED BRICK AND MATCHING REPLACEMENT BRICK WHERE NECESSARY. INSTALL REPLACEMENT CAST STONE CAPS TO MATCH

- (8) INSTALL FLEXIBLE JOINT.
- (10) INSTALL BALUSTRADE AND GUARDRAILS AT PORCH AND
- (12) REPAIR AND PAINT SALVAGED WOOD FRAME AND INSTALL NEW PANEL IN PLACE OF MESH. REINSTALL.
- INSIDE OF FRIEZE, AND ARCHITRAVE, WITH CONSOLIDANT. PAINT.
- DRAINAGE AWAY FROM THE BUILDING. PAINT EXISTING PIECES THAT ARE REUSED.
- SEE DOOR SCHEDULE ON A601 FOR HARDWARE.
- (17) INSTALL PERMANENT DOOR STOP.
- (18) INSTALL LIGHT. SEE SCHEDULE.
- (19) RESTORE AND REINSTALL LAMPS. PAINT METAL AND PROVIDE NEW GLOBES.
- (20) REGRADE DISTURBED AREA AROUND BOTTOM OF STAIRS AND PIERS, REPLACE SOD.
- AND INFILL WHERE CONCRETE WAS REMOVED. SEE STRUCTURAL FOR EXTENT AND FILL REQUIREMENTS. SEE CIVIL FOR REGRADING.
- (24) URINAL. SEE SCHEDULE.
- (25) SINK AND FAUCET. SEE SCHEDULE.
- (27) TOILET ROOM PARTITIONS AND DOORS.
- (28) CONSTRUCT WALL.
- (31) REINSTALL SALVAGED QUARRY TILE AND INSTALL NEW TILE WHERE NECESSARY.
- (32) PAINT METAL CORNICE AND PARAPET CAP.
- (33) REPAIR DAMAGE TO CONCRETE FROM PIPES AND CONDUIT. SEAL OPENING IN MASONRY AROUND
- (34) PAINT WOOD TRIM AND CORNICE OF BOW WINDOW
- (36) REPAIR WOOD AT BOTTOM OF CORNICE.
- (37) MODIFY THRESHOLD AND SEAL JOINTS.

CONSTRUCTION NOTES







ORIGINAL.

(5) REPLACE CAST STONE AT STAIRS AND TOP BAND AT PORCH. PAINT (DO NOT PAINT STEPS).

(6) REINSTALL STEPS.

(7) RECONSTRUCT CONCRETE WALK.

(9) CONSTRUCT NEW WALL AND INFILL AREA BENEATH STAIRS. SEE STRUCTURAL.

STEPS. INSTALL HANDRAILS AT STEPS.

(11) INSTALL PANELS AT PORCH OPENINGS.

(13) REPAIR WOOD ENTABLATURE, INCLUDING CORNICE,

(14) REPAIR AND EXTEND DOWNSPOUTS TO PROVIDE

(15) CLEAN CAST STONE AROUND DOOR AND THRESHOLD.

(16) REPAIR DOORS AND PAINT, INCLUDING WOOD TRIM.

(21) INFILL OPENINGS WITH CONCRETE MASONRY UNITS.

- (22) WATERPROOF EXTERIOR OF BUILDING BELOW GRADE
- (23) TOILET FIXTURE. SEE SCHEDULE.

- (26) TOILET ROOM EQUIPMENT. SEE ELEVATIONS AND

- 29) DOOR. SEE SCHEDULE.
- (30) WINDOW. SEE SCHEDULE.
- PAINT WOOD ON EXTERIOR SIDE OF EXISTING WINDOW/DOOR.

Thompson Moon, HVAC Upgrade, a

HoH

Memorial H

O L

M C

 $\wp_{\scriptscriptstyle \Pi}$

ONALD

A205

LOWER LEVEL

RCP

1 FIRST FLOOR RCP

A206 1/4" = 1'-0"

CONSTRUCTION NOTES


- (1) POUR CONCRETE FOOTINGS AND PIER BASE.
- (2) RESET STONE AT PORCH EDGE AND INSTALL
- REPLACEMENT CAST STONE TO MATCH ORIGINAL.
- (3) INSTALL DORIC COLUMNS AND REINSTALL SALVAGED
- (4) REBUILD STAIR WALLS USING SALVAGED BRICK AND MATCHING REPLACEMENT BRICK WHERE NECESSARY. INSTALL REPLACEMENT CAST STONE CAPS TO MATCH ORIGINAL.
- (5) REPLACE CAST STONE AT STAIRS AND TOP BAND AT PORCH. PAINT (DO NOT PAINT STEPS).
- 6 REINSTALL STEPS.
- (7) RECONSTRUCT CONCRETE WALK.
- (8) INSTALL FLEXIBLE JOINT.
- (9) CONSTRUCT NEW WALL AND INFILL AREA BENEATH STAIRS. SEE STRUCTURAL.
- (10) INSTALL BALUSTRADE AND GUARDRAILS AT PORCH AND STEPS. INSTALL HANDRAILS AT STEPS.
- (11) INSTALL PANELS AT PORCH OPENINGS.
- (12) REPAIR AND PAINT SALVAGED WOOD FRAME AND INSTALL NEW PANEL IN PLACE OF MESH. REINSTALL.
- (13) REPAIR WOOD ENTABLATURE, INCLUDING CORNICE, INSIDE OF FRIEZE, AND ARCHITRAVE, WITH CONSOLIDANT. PAINT.
- (14) REPAIR AND EXTEND DOWNSPOUTS TO PROVIDE DRAINAGE AWAY FROM THE BUILDING. PAINT EXISTING PIECES THAT ARE REUSED.
- (15) CLEAN CAST STONE AROUND DOOR AND THRESHOLD.
- (16) REPAIR DOORS AND PAINT, INCLUDING WOOD TRIM. SEE DOOR SCHEDULE ON A601 FOR HARDWARE.
- (17) INSTALL PERMANENT DOOR STOP.
- (18) INSTALL LIGHT. SEE SCHEDULE.
- (19) RESTORE AND REINSTALL LAMPS. PAINT METAL AND PROVIDE NEW GLOBES.
- (20) REGRADE DISTURBED AREA AROUND BOTTOM OF STAIRS AND PIERS, REPLACE SOD.
- (21) INFILL OPENINGS WITH CONCRETE MASONRY UNITS.
- (22) WATERPROOF EXTERIOR OF BUILDING BELOW GRADE AND INFILL WHERE CONCRETE WAS REMOVED. SEE STRUCTURAL FOR EXTENT AND FILL REQUIREMENTS. SEE CIVIL FOR REGRADING.
- (23) TOILET FIXTURE. SEE SCHEDULE.
- (24) URINAL. SEE SCHEDULE.
- (25) SINK AND FAUCET. SEE SCHEDULE.
- (26) TOILET ROOM EQUIPMENT. SEE ELEVATIONS AND
- (27) TOILET ROOM PARTITIONS AND DOORS.
- (28) CONSTRUCT WALL.
- 29) DOOR. SEE SCHEDULE.
- (30) WINDOW. SEE SCHEDULE.
- (31) REINSTALL SALVAGED QUARRY TILE AND INSTALL NEW TILE WHERE NECESSARY.
- (32) PAINT METAL CORNICE AND PARAPET CAP.
- (33) REPAIR DAMAGE TO CONCRETE FROM PIPES AND CONDUIT. SEAL OPENING IN MASONRY AROUND
- (34) PAINT WOOD TRIM AND CORNICE OF BOW WINDOW
- (35) PAINT WOOD ON EXTERIOR SIDE OF EXISTING WINDOW/DOOR.
- (36) REPAIR WOOD AT BOTTOM OF CORNICE.
- (37) MODIFY THRESHOLD AND SEAL JOINTS.



O N S

M O

 $\wp_{\scriptscriptstyle \Pi}$




HaH Memorial H


FIRST FLOOR RCP

CONSTRUCTION NOTES

- 1) POUR CONCRETE FOOTINGS AND PIER BASE.
- 2 RESET STONE AT PORCH EDGE AND INSTALL
- REPLACEMENT CAST STONE TO MATCH ORIGINAL.
- 3 INSTALL DORIC COLUMNS AND REINSTALL SALVAGED BASES.
- 4 REBUILD STAIR WALLS USING SALVAGED BRICK AND MATCHING REPLACEMENT BRICK WHERE NECESSARY. INSTALL REPLACEMENT CAST STONE CAPS TO MATCH ORIGINAL.
- 5 REPLACE CAST STONE AT STAIRS AND TOP BAND AT PORCH. PAINT (DO NOT PAINT STEPS).
- (6) REINSTALL STEPS.
- (7) RECONSTRUCT CONCRETE WALK.
- (8) INSTALL FLEXIBLE JOINT.
- 9 CONSTRUCT NEW WALL AND INFILL AREA BENEATH STAIRS. SEE STRUCTURAL.
- 10 INSTALL BALUSTRADE AND GUARDRAILS AT PORCH AND STEPS. INSTALL HANDRAILS AT STEPS.
- (11) INSTALL PANELS AT PORCH OPENINGS.
- (12) REPAIR AND PAINT SALVAGED WOOD FRAME AND INSTALL NEW PANEL IN PLACE OF MESH. REINSTALL.
- 13 REPAIR WOOD ENTABLATURE, INCLUDING CORNICE, INSIDE OF FRIEZE, AND ARCHITRAVE, WITH CONSOLIDANT. PAINT.
- REPAIR AND EXTEND DOWNSPOUTS TO PROVIDE DRAINAGE AWAY FROM THE BUILDING. PAINT EXISTING PIECES THAT ARE REUSED.
- (15) CLEAN CAST STONE AROUND DOOR AND THRESHOLD.
- (16) REPAIR DOORS AND PAINT, INCLUDING WOOD TRIM. SEE DOOR SCHEDULE ON A601 FOR HARDWARE.
- (17) INSTALL PERMANENT DOOR STOP.
- (18) INSTALL LIGHT. SEE SCHEDULE.
- 19 RESTORE AND REINSTALL LAMPS. PAINT METAL AND PROVIDE NEW GLOBES.
- 20 REGRADE DISTURBED AREA AROUND BOTTOM OF STAIRS AND PIERS, REPLACE SOD.
- (21) INFILL OPENINGS WITH CONCRETE MASONRY UNITS.
- WATERPROOF EXTERIOR OF BUILDING BELOW GRADE AND INFILL WHERE CONCRETE WAS REMOVED. SEE STRUCTURAL FOR EXTENT AND FILL REQUIREMENTS. SEE CIVIL FOR REGRADING.
- (23) TOILET FIXTURE. SEE SCHEDULE.
- 24) URINAL. SEE SCHEDULE.
- (25) SINK AND FAUCET. SEE SCHEDULE.
- (26) TOILET ROOM EQUIPMENT. SEE ELEVATIONS AND SCHEDULE.
- (27) TOILET ROOM PARTITIONS AND DOORS.
- (28) CONSTRUCT WALL.
- (29) DOOR. SEE SCHEDULE.
- 30 WINDOW. SEE SCHEDULE.
- REINSTALL SALVAGED QUARRY TILE AND INSTALL NEW TILE WHERE NECESSARY.
- 32) PAINT METAL CORNICE AND PARAPET CAP.
- (33) REPAIR DAMAGE TO CONCRETE FROM PIPES AND CONDUIT. SEAL OPENING IN MASONRY AROUND PIPES.
- PAINT WOOD TRIM AND CORNICE OF BOW WINDOW EXTERIOR.
- (35) PAINT WOOD ON EXTERIOR SIDE OF EXISTING WINDOW/DOOR.
- (36) REPAIR WOOD AT BOTTOM OF CORNICE.
- (37) MODIFY THRESHOLD AND SEAL JOINTS.



ONALD & MACK
H I T E C T S
H STREET STE ZT Z MINNEAPOULS MINNESOTA 5 5 4 1 5



Memorial Hall de, and Addition

Saint Paul MN 55104

1824 Marshall Avenue, S

SECOND

FLOOR

RCP


CONSTRUCTION NOTES

- (1) POUR CONCRETE FOOTINGS AND PIER BASE.
- (2) RESET STONE AT PORCH EDGE AND INSTALL
- REPLACEMENT CAST STONE TO MATCH ORIGINAL.
- 3 INSTALL DORIC COLUMNS AND REINSTALL SALVAGED BASES.
- 4 REBUILD STAIR WALLS USING SALVAGED BRICK AND MATCHING REPLACEMENT BRICK WHERE NECESSARY. INSTALL REPLACEMENT CAST STONE CAPS TO MATCH ORIGINAL.
- 5 REPLACE CAST STONE AT STAIRS AND TOP BAND AT PORCH. PAINT (DO NOT PAINT STEPS).
- (6) REINSTALL STEPS.
- (7) RECONSTRUCT CONCRETE WALK.
- (8) INSTALL FLEXIBLE JOINT.
- 9 CONSTRUCT NEW WALL AND INFILL AREA BENEATH STAIRS. SEE STRUCTURAL.
- 10 INSTALL BALUSTRADE AND GUARDRAILS AT PORCH AND STEPS. INSTALL HANDRAILS AT STEPS.
- (11) INSTALL PANELS AT PORCH OPENINGS.
- (12) REPAIR AND PAINT SALVAGED WOOD FRAME AND INSTALL NEW PANEL IN PLACE OF MESH. REINSTALL.
- REPAIR WOOD ENTABLATURE, INCLUDING CORNICE, INSIDE OF FRIEZE, AND ARCHITRAVE, WITH CONSOLIDANT. PAINT.
- REPAIR AND EXTEND DOWNSPOUTS TO PROVIDE DRAINAGE AWAY FROM THE BUILDING. PAINT EXISTING PIECES THAT ARE REUSED.
- (15) CLEAN CAST STONE AROUND DOOR AND THRESHOLD.
- REPAIR DOORS AND PAINT, INCLUDING WOOD TRIM.
 SEE DOOR SCHEDULE ON A601 FOR HARDWARE.
- (17) INSTALL PERMANENT DOOR STOP.
- (18) INSTALL LIGHT. SEE SCHEDULE.
- RESTORE AND REINSTALL LAMPS. PAINT METAL AND PROVIDE NEW GLOBES.
- 20 REGRADE DISTURBED AREA AROUND BOTTOM OF STAIRS AND PIERS, REPLACE SOD.
- (21) INFILL OPENINGS WITH CONCRETE MASONRY UNITS.
- WATERPROOF EXTERIOR OF BUILDING BELOW GRADE AND INFILL WHERE CONCRETE WAS REMOVED. SEE STRUCTURAL FOR EXTENT AND FILL REQUIREMENTS. SEE CIVIL FOR REGRADING.
- 23) TOILET FIXTURE. SEE SCHEDULE.
- 24) URINAL. SEE SCHEDULE.
- 25) SINK AND FAUCET. SEE SCHEDULE.
- (26) TOILET ROOM EQUIPMENT. SEE ELEVATIONS AND SCHEDULE.
- 27) TOILET ROOM PARTITIONS AND DOORS.
- (28) CONSTRUCT WALL.
- 29) DOOR. SEE SCHEDULE.
- (30) WINDOW. SEE SCHEDULE.
- REINSTALL SALVAGED QUARRY TILE AND INSTALL NEW TILE WHERE NECESSARY.
- 32) PAINT METAL CORNICE AND PARAPET CAP.
- REPAIR DAMAGE TO CONCRETE FROM PIPES AND CONDUIT. SEAL OPENING IN MASONRY AROUND PIPES.
- PAINT WOOD TRIM AND CORNICE OF BOW WINDOW EXTERIOR.
- (35) PAINT WOOD ON EXTERIOR SIDE OF EXISTING WINDOW/DOOR.
- 36 REPAIR WOOD AT BOTTOM OF CORNICE.
- (37) MODIFY THRESHOLD AND SEAL JOINTS.

ONALD & MA

O - X

The arby centify that this plan, specification, of the State of Minnesola



rial Hall ddition

s Thompson Memorial Fion, HVAC Upgrade, and Addition

Rehabili

THIRD


RCP


FLOOR

1 NORTH DEMOLITION ELEVATION

- \bigcirc REMOVE AND SALVAGE LIGHT POSTS.
- $\langle 2 \rangle$ remove porch railings and stair handrails.
- 3 REMOVE AND SALVAGE STONE STEPS.
- 4 REMOVE QUARRY TILES, SALVAGE WHERE POSSIBLE.
- $\langle 5 \rangle$ remove mesh screen and salvage frame.
- $\langle 6 \rangle$ dismantle piers, including concrete bases. SALVAGE BRICK.
- 7 DISMANTLE STAIR WALLS. SALVAGE BRICK AND DISPOSE OF CAST STONE CAPS. CONCRETE FOUNDATION AND BASE TO REMAIN.
- 8 DEMOLISH SIDEWALK (CITY SIDEWALK TO REMAIN).
- $\langle 9 \rangle$ remove brick infill in Porch openings and DEMOLISH CONCRETE INFILL. TAKE CARE NOT TO DAMAGE ORIGINAL SURROUNDING MASONRY AND CONCRETE.
- 10 DEMOLISH WALL AND NOTIFY ARCHITECT. ARCHITECT TO INSPECT AREA BENEATH STAIRS BEFORE INFILLED.
- $\langle 1 1 \rangle$ install temporary shoring at porch roof and DEMOLISH COLUMNS. SALVAGE CAST STONE BASES FOR REINSTALLATION.
- 12) REMOVE CAST STONE AT PORCH EDGE. REMOVE AND SALVAGE STONE BENEATH FOR REINSTALLATION.
- $\langle 13 \rangle$ Salvage door for reinstallation.
- (14) REMOVE ALL EXISTING TOILET ROOM PARTITIONS AND STALL DOORS.
- (15) REMOVE TOILET ROOM FIXTURES.
- REMOVE WALLS AND CONCRETE AT GRADE. SEE STRUCTURAL DRAWINGS FOR EXTENT BELOW GRADE.
- $\langle \overline{17} \rangle$ remove metal bars from windows.
- 18 REMOVE WINDOW INFILL PANELS.
- (19) SALVAGE WINDOW GLAZING AND FRAME, RETURN TO OWNER. SELECTIVELY REMOVE PORTION OF EXTERIOR WALL NECESSARY TO RECEIVE DOOR.
- 20 REMOVE WALL.
- $\langle \overline{21} \rangle$ REMOVE DOOR.
- 22 REMOVE RADIATOR.
- 23 REMOVE KITCHEN APPLIANCES AND SINK.
- $\overline{\langle 24 \rangle}$ remove countertops.
- 25 REMOVE CEILING TILES.
- 26 REMOVE LIGHT FIXTURE.
- 27) DEMOLISH GARAGE.

REMOVAL KEY





BRICK MASONRY TO REMAIN

Charles Thompson Memorial Hall Rehabilitation, HVAC Upgrade, and Addition

 $\sum_{\mathbf{A}} \mathcal{A}$

 $\mathcal{O}_{^{\square}}$

ONALD

 C_{O}^{O}

NORTH DEMOLITION ELEVATION

30% REVIEW SET



1 EAST DEMOLITION ELEVATION

REMOVAL NOTES

- \bigcirc REMOVE AND SALVAGE LIGHT POSTS.
- $\langle 2 \rangle$ remove porch railings and stair handrails.
- 3 REMOVE AND SALVAGE STONE STEPS.
- 4 REMOVE QUARRY TILES, SALVAGE WHERE POSSIBLE.
- (5) REMOVE MESH SCREEN AND SALVAGE FRAME.
- (6) DISMANTLE PIERS, INCLUDING CONCRETE BASES. SALVAGE BRICK.
- 7 DISMANTLE STAIR WALLS. SALVAGE BRICK AND DISPOSE OF CAST STONE CAPS. CONCRETE FOUNDATION AND BASE TO REMAIN.
- 8 DEMOLISH SIDEWALK (CITY SIDEWALK TO REMAIN).
- $\langle 9 \rangle$ remove brick infill in Porch openings and DEMOLISH CONCRETE INFILL. TAKE CARE NOT TO DAMAGE ORIGINAL SURROUNDING MASONRY AND CONCRETE.
- 10 DEMOLISH WALL AND NOTIFY ARCHITECT. ARCHITECT TO INSPECT AREA BENEATH STAIRS BEFORE INFILLED.
- 11) INSTALL TEMPORARY SHORING AT PORCH ROOF AND DEMOLISH COLUMNS. SALVAGE CAST STONE BASES FOR REINSTALLATION.
- 12) REMOVE CAST STONE AT PORCH EDGE. REMOVE AND SALVAGE STONE BENEATH FOR REINSTALLATION.
- $\langle 13 \rangle$ Salvage door for reinstallation.
- $\langle \overline{14} \rangle$ remove all existing toilet room partitions and STALL DOORS.
- 15 REMOVE TOILET ROOM FIXTURES.
- REMOVE WALLS AND CONCRETE AT GRADE. SEE STRUCTURAL DRAWINGS FOR EXTENT BELOW GRADE.
- $\langle \overline{17} \rangle$ remove metal bars from windows.
- (18) REMOVE WINDOW INFILL PANELS.
- (19) SALVAGE WINDOW GLAZING AND FRAME, RETURN TO OWNER. SELECTIVELY REMOVE PORTION OF EXTERIOR WALL NECESSARY TO RECEIVE DOOR.
- 20 REMOVE WALL.
- $\langle 21 \rangle$ REMOVE DOOR.
- 22 REMOVE RADIATOR.
- 23 REMOVE KITCHEN APPLIANCES AND SINK.
- 24) REMOVE COUNTERTOPS.
- 25) REMOVE CEILING TILES.
- 26 REMOVE LIGHT FIXTURE.
- 27 DEMOLISH GARAGE.

REMOVAL KEY

DEMOLISH MASONRY, SALVAGE AS NOTED

- REMOVE/DISMANTLE

DEMOLISH MASONRY, SALVAGE AS NOTED BRICK MASONRY TO REMAIN (10% REPOINTING, TYPICAL)

Charles Thompson Memorial Hall Rehabilitation, HVAC Upgrade, and Addition

 $\sum_{\mathbf{A}} \mathcal{A}$

 $\mathcal{O}_{^{\square}}$

ONALD

 C_{O}^{O}

EAST DEMOLITION

ELEVATION

30% REVIEW SET A301

1 | SOUTH DEMOLITION ELEVATION


- \bigcirc REMOVE AND SALVAGE LIGHT POSTS.
- $\langle 2 \rangle$ remove porch railings and stair handrails.
- 3 REMOVE AND SALVAGE STONE STEPS.
- 4 REMOVE QUARRY TILES, SALVAGE WHERE POSSIBLE.
- $\langle 5 \rangle$ remove mesh screen and salvage frame.
- (6) DISMANTLE PIERS, INCLUDING CONCRETE BASES. SALVAGE BRICK.
- 7 DISMANTLE STAIR WALLS. SALVAGE BRICK AND DISPOSE OF CAST STONE CAPS. CONCRETE FOUNDATION AND BASE TO REMAIN.
- 8 DEMOLISH SIDEWALK (CITY SIDEWALK TO REMAIN).
- 9 REMOVE BRICK INFILL IN PORCH OPENINGS AND DEMOLISH CONCRETE INFILL. TAKE CARE NOT TO DAMAGE ORIGINAL SURROUNDING MASONRY AND CONCRETE.
- 10 DEMOLISH WALL AND NOTIFY ARCHITECT. ARCHITECT TO INSPECT AREA BENEATH STAIRS BEFORE INFILLED.
- (11) INSTALL TEMPORARY SHORING AT PORCH ROOF AND DEMOLISH COLUMNS. SALVAGE CAST STONE BASES FOR REINSTALLATION.
- 12 REMOVE CAST STONE AT PORCH EDGE. REMOVE AND SALVAGE STONE BENEATH FOR REINSTALLATION.
- (13) SALVAGE DOOR FOR REINSTALLATION.
- 14) REMOVE ALL EXISTING TOILET ROOM PARTITIONS AND STALL DOORS.
- (15) REMOVE TOILET ROOM FIXTURES.
- 16) remove walls and concrete at grade. See STRUCTURAL DRAWINGS FOR EXTENT BELOW GRADE.
- $\langle \overline{17} \rangle$ remove metal bars from windows.
- 18 REMOVE WINDOW INFILL PANELS.
- (19) SALVAGE WINDOW GLAZING AND FRAME, RETURN TO OWNER. SELECTIVELY REMOVE PORTION OF EXTERIOR WALL NECESSARY TO RECEIVE DOOR.
- 20 REMOVE WALL.
- $\langle 21 \rangle$ REMOVE DOOR.
- 22 REMOVE RADIATOR.
- 23 REMOVE KITCHEN APPLIANCES AND SINK.
- 24) REMOVE COUNTERTOPS.
- 25 REMOVE CEILING TILES.
- 26) REMOVE LIGHT FIXTURE.

27 DEMOLISH GARAGE.





REMOVE/DISMANTLE



HaH

 $\sum_{\mathbf{A}} \mathcal{A}$

 $\mathcal{O}_{^{\square}}$

ONALD

SOUTH DEMOLITION ELEVATION

30% REVIEW SET

A302 1/4" = 1'-0"



1 WEST DEMOLITION ELEVATION

REMOVAL NOTES


- \bigcirc REMOVE AND SALVAGE LIGHT POSTS.
- $\langle 2 \rangle$ remove porch railings and stair handrails.
- 3 REMOVE AND SALVAGE STONE STEPS.
- 4 REMOVE QUARRY TILES, SALVAGE WHERE POSSIBLE.
- (5) REMOVE MESH SCREEN AND SALVAGE FRAME.
- (6) DISMANTLE PIERS, INCLUDING CONCRETE BASES. SALVAGE BRICK.
- 7 DISMANTLE STAIR WALLS. SALVAGE BRICK AND DISPOSE OF CAST STONE CAPS. CONCRETE FOUNDATION AND BASE TO REMAIN.
- 8 DEMOLISH SIDEWALK (CITY SIDEWALK TO REMAIN).
- $\langle 9 \rangle$ remove brick infill in Porch openings and DEMOLISH CONCRETE INFILL. TAKE CARE NOT TO DAMAGE ORIGINAL SURROUNDING MASONRY AND CONCRETE.
- 10 DEMOLISH WALL AND NOTIFY ARCHITECT. ARCHITECT TO INSPECT AREA BENEATH STAIRS BEFORE INFILLED.
- 11) INSTALL TEMPORARY SHORING AT PORCH ROOF AND DEMOLISH COLUMNS. SALVAGE CAST STONE BASES FOR REINSTALLATION.
- 12) REMOVE CAST STONE AT PORCH EDGE. REMOVE AND SALVAGE STONE BENEATH FOR REINSTALLATION.
- $\langle 13 \rangle$ Salvage door for reinstallation.
- (14) REMOVE ALL EXISTING TOILET ROOM PARTITIONS AND STALL DOORS.
- (15) REMOVE TOILET ROOM FIXTURES.
- REMOVE WALLS AND CONCRETE AT GRADE. SEE STRUCTURAL DRAWINGS FOR EXTENT BELOW GRADE.
- $\langle \overline{17} \rangle$ remove metal bars from windows.
- (18) REMOVE WINDOW INFILL PANELS.
- (19) SALVAGE WINDOW GLAZING AND FRAME, RETURN TO OWNER. SELECTIVELY REMOVE PORTION OF EXTERIOR WALL NECESSARY TO RECEIVE DOOR.
- 20 REMOVE WALL.
- $\langle 21 \rangle$ REMOVE DOOR.
- 22 REMOVE RADIATOR.
- 23 REMOVE KITCHEN APPLIANCES AND SINK.
- 24) REMOVE COUNTERTOPS.
- 25 REMOVE CEILING TILES.
- 26 REMOVE LIGHT FIXTURE.
- 27) DEMOLISH GARAGE.

REMOVAL KEY



DEMOLISH MASONRY, SALVAGE AS NOTED

- REMOVE/DISMANTLE



SALVAGE AS NOTED BRICK MASONRY TO REMAIN (10% REPOINTING, TYPICAL)

WEST


30% REVIEW SET

A303

DEMOLITION

ELEVATION

Charles Thompson Memorial Hall Rehabilitation, HVAC Upgrade, and Addition



 $\mathcal{O}_{^{\square}}$

ONALD

 C_{O}^{O}

ASSUME 10% REPOINTING OF ENTIRE BRICK FACADE UNLESS OTHER WORK IS NOTED.



CONSTRUCTION NOTES

CONSTRUCTION KEY

25% REPOINT

50% REPOINT

100% REPOINT

CLEAN BRICK MASONRY

REPAIR CHIPPED CAST STONE

REPOINT/SEAL JOINTS AT CAST STONE

CLEAN STONE/CAST STONE, REPOINT/SEAL JOINTS

NEW BRICK MASONRY

reconstruct brick masonry

- 1 POUR CONCRETE FOOTINGS AND PIER BASE.
- 2 RESET STONE AT PORCH EDGE AND INSTALL
- REPLACEMENT CAST STONE TO MATCH ORIGINAL.
- 3 INSTALL DORIC COLUMNS AND REINSTALL SALVAGED BASES.
- 4 REBUILD STAIR WALLS USING SALVAGED BRICK AND MATCHING REPLACEMENT BRICK WHERE NECESSARY. INSTALL REPLACEMENT CAST STONE CAPS TO MATCH ORIGINAL.
- 5 REPLACE CAST STONE AT STAIRS AND TOP BAND AT PORCH. PAINT (DO NOT PAINT STEPS).
- (6) REINSTALL STEPS.
- (7) RECONSTRUCT CONCRETE WALK.
- (8) INSTALL FLEXIBLE JOINT.
- 9 CONSTRUCT NEW WALL AND INFILL AREA BENEATH STAIRS. SEE STRUCTURAL.
- (10) INSTALL BALUSTRADE AND GUARDRAILS AT PORCH AND STEPS. INSTALL HANDRAILS AT STEPS.
- (11) INSTALL PANELS AT PORCH OPENINGS.
- REPAIR AND PAINT SALVAGED WOOD FRAME AND INSTALL NEW PANEL IN PLACE OF MESH. REINSTALL.
- REPAIR WOOD ENTABLATURE, INCLUDING CORNICE, INSIDE OF FRIEZE, AND ARCHITRAVE, WITH CONSOLIDANT. PAINT.
- REPAIR AND EXTEND DOWNSPOUTS TO PROVIDE DRAINAGE AWAY FROM THE BUILDING. PAINT EXISTING PIECES THAT ARE REUSED.
- (15) CLEAN CAST STONE AROUND DOOR AND THRESHOLD.
- (16) REPAIR DOORS AND PAINT, INCLUDING WOOD TRIM.
 SEE DOOR SCHEDULE ON A601 FOR HARDWARE.
- (17) INSTALL PERMANENT DOOR STOP.
- (18) INSTALL LIGHT. SEE SCHEDULE.
- RESTORE AND REINSTALL LAMPS. PAINT METAL AND PROVIDE NEW GLOBES.
- 20 REGRADE DISTURBED AREA AROUND BOTTOM OF STAIRS AND PIERS, REPLACE SOD.
- (21) INFILL OPENINGS WITH CONCRETE MASONRY UNITS.
- WATERPROOF EXTERIOR OF BUILDING BELOW GRADE AND INFILL WHERE CONCRETE WAS REMOVED. SEE STRUCTURAL FOR EXTENT AND FILL REQUIREMENTS. SEE CIVIL FOR REGRADING.
- (23) TOILET FIXTURE. SEE SCHEDULE.
- 24) URINAL. SEE SCHEDULE.
- (25) SINK AND FAUCET. SEE SCHEDULE.
- (26) TOILET ROOM EQUIPMENT. SEE ELEVATIONS AND SCHEDULE.
- (27) TOILET ROOM PARTITIONS AND DOORS.
- 28 CONSTRUCT WALL.
- (29) DOOR. SEE SCHEDULE.
- (30) WINDOW. SEE SCHEDULE.
- REINSTALL SALVAGED QUARRY TILE AND INSTALL NEW TILE WHERE NECESSARY.
- (32) PAINT METAL CORNICE AND PARAPET CAP.
- REPAIR DAMAGE TO CONCRETE FROM PIPES AND CONDUIT. SEAL OPENING IN MASONRY AROUND PIPES.
- (34) PAINT WOOD TRIM AND CORNICE OF BOW WINDOW EXTERIOR.
- PAINT WOOD ON EXTERIOR SIDE OF EXISTING WINDOW/DOOR.
- (36) REPAIR WOOD AT BOTTOM OF CORNICE.
- 37 MODIFY THRESHOLD AND SEAL JOINTS.

30% REVIEW SET

MACDONALD
A R C H I T

 \triangleleft

 $\sum_{i} O_{i}$

 Ω \square

s Thompson Memorial Hall

Cnarles Inompson Rehabilitation, HVAC Upgra

NORTH
CONSTRUCTION
ELEVATION

SHEET NOTES

ASSUME 10% REPOINTING OF ENTIRE BRICK FACADE UNLESS OTHER WORK IS NOTED.



CONSTRUCTION KEY CONS

NEW BRICK MASONRY

RECONSTRUCT BRICK MASONRY

RECONSTRUCT BRICK MASONR

25% REPOINT

50% REPOINT

100% REPOINT

CLEAN BRICK MASONRY

CLEAN STONE/CAST STONE, REPOINT/SEAL JOINTS

REPAIR CHIPPED CAST STONE

REPOINT/SEAL JOINTS AT CAST STONE

CONCRETE

REPLACE HISTORIC CAST STONE

REPAIR CRACK/HOLE IN CONCRETE/MASONRY

CONSTRUCTION NOTES

- 1) POUR CONCRETE FOOTINGS AND PIER BASE.
- 2 RESET STONE AT PORCH EDGE AND INSTALL REPLACEMENT CAST STONE TO MATCH ORIGINAL.
- 3 INSTALL DORIC COLUMNS AND REINSTALL SALVAGED
- 4 REBUILD STAIR WALLS USING SALVAGED BRICK AND MATCHING REPLACEMENT BRICK WHERE NECESSARY. INSTALL REPLACEMENT CAST STONE CAPS TO MATCH ORIGINAL.
- 5 REPLACE CAST STONE AT STAIRS AND TOP BAND AT PORCH. PAINT (DO NOT PAINT STEPS).
- (6) REINSTALL STEPS.
- (7) RECONSTRUCT CONCRETE WALK.
- (8) INSTALL FLEXIBLE JOINT.
- 9 CONSTRUCT NEW WALL AND INFILL AREA BENEATH STAIRS. SEE STRUCTURAL.
- (10) INSTALL BALUSTRADE AND GUARDRAILS AT PORCH AND STEPS. INSTALL HANDRAILS AT STEPS.
- (11) INSTALL PANELS AT PORCH OPENINGS.
- REPAIR AND PAINT SALVAGED WOOD FRAME AND INSTALL NEW PANEL IN PLACE OF MESH. REINSTALL.
- REPAIR WOOD ENTABLATURE, INCLUDING CORNICE, INSIDE OF FRIEZE, AND ARCHITRAVE, WITH CONSOLIDANT. PAINT.
- REPAIR AND EXTEND DOWNSPOUTS TO PROVIDE DRAINAGE AWAY FROM THE BUILDING. PAINT EXISTING PIECES THAT ARE REUSED.
- (15) CLEAN CAST STONE AROUND DOOR AND THRESHOLD.
- (16) REPAIR DOORS AND PAINT, INCLUDING WOOD TRIM. SEE DOOR SCHEDULE ON A601 FOR HARDWARE.
- (17) INSTALL PERMANENT DOOR STOP.
- (18) INSTALL LIGHT. SEE SCHEDULE.
- RESTORE AND REINSTALL LAMPS. PAINT METAL AND PROVIDE NEW GLOBES.
- 20 REGRADE DISTURBED AREA AROUND BOTTOM OF STAIRS AND PIERS, REPLACE SOD.
- (21) INFILL OPENINGS WITH CONCRETE MASONRY UNITS.
- WATERPROOF EXTERIOR OF BUILDING BELOW GRADE AND INFILL WHERE CONCRETE WAS REMOVED. SEE STRUCTURAL FOR EXTENT AND FILL REQUIREMENTS. SEE CIVIL FOR REGRADING.
- (23) TOILET FIXTURE. SEE SCHEDULE.
- 24) URINAL. SEE SCHEDULE.
- 25) SINK AND FAUCET. SEE SCHEDULE.
- (26) TOILET ROOM EQUIPMENT. SEE ELEVATIONS AND SCHEDULE.
- (27) TOILET ROOM PARTITIONS AND DOORS.
- 28 CONSTRUCT WALL.
- 29 DOOR. SEE SCHEDULE.
- 30 WINDOW. SEE SCHEDULE.
- (31) REINSTALL SALVAGED QUARRY TILE AND INSTALL NEW TILE WHERE NECESSARY.
- (32) PAINT METAL CORNICE AND PARAPET CAP.
- REPAIR DAMAGE TO CONCRETE FROM PIPES AND CONDUIT. SEAL OPENING IN MASONRY AROUND
- PAINT WOOD TRIM AND CORNICE OF BOW WINDOW
- 35) PAINT WOOD ON EXTERIOR SIDE OF EXISTING WINDOW/DOOR.
- (36) REPAIR WOOD AT BOTTOM OF CORNICE.
- 37) MODIFY THRESHOLD AND SEAL JOINTS.

MACDONALD & MA

A R C H I T E C

400 SOUTH FOURTH STREET STE 712 MINNESPOTA

P612 341 4051 F 612 337 5843 WWW.MMARCH

es Ihompson Memorial ation, HVAC Upgrade, and Addition

Hall

EAST
CONSTRUCTION
ELEVATION

A305

Elevation: 0'-0"

ASSUME 10% REPOINTING OF ENTIRE BRICK FACADE UNLESS OTHER WORK IS NOTED.

NEW BRICK MASONRY RECONSTRUCT BRICK MASONRY 25% REPOINT 50% REPOINT 100% REPOINT CLEAN BRICK MASONRY REPAIR CHIPPED CAST STONE REPOINT/SEAL JOINTS AT CAST STONE CONCRETE REPLACE HISTORIC CAST STONE

CONSTRUCTION KEY

CLEAN STONE/CAST STONE, REPOINT/SEAL JOINTS REPAIR CRACK/HOLE IN CONCRETE/MASONRY

CONSTRUCTION NOTES

- (1) POUR CONCRETE FOOTINGS AND PIER BASE.
- (2) RESET STONE AT PORCH EDGE AND INSTALL REPLACEMENT CAST STONE TO MATCH ORIGINAL.
- (3) INSTALL DORIC COLUMNS AND REINSTALL SALVAGED
- (4) REBUILD STAIR WALLS USING SALVAGED BRICK AND MATCHING REPLACEMENT BRICK WHERE NECESSARY. INSTALL REPLACEMENT CAST STONE CAPS TO MATCH ORIGINAL.
- (5) REPLACE CAST STONE AT STAIRS AND TOP BAND AT PORCH. PAINT (DO NOT PAINT STEPS).
- (6) REINSTALL STEPS.
- (7) RECONSTRUCT CONCRETE WALK.
- (8) INSTALL FLEXIBLE JOINT.
- (9) CONSTRUCT NEW WALL AND INFILL AREA BENEATH STAIRS. SEE STRUCTURAL.
- (10) INSTALL BALUSTRADE AND GUARDRAILS AT PORCH AND STEPS. INSTALL HANDRAILS AT STEPS.
- (11) INSTALL PANELS AT PORCH OPENINGS.
- (12) REPAIR AND PAINT SALVAGED WOOD FRAME AND INSTALL NEW PANEL IN PLACE OF MESH. REINSTALL.
- (13) REPAIR WOOD ENTABLATURE, INCLUDING CORNICE, INSIDE OF FRIEZE, AND ARCHITRAVE, WITH CONSOLIDANT. PAINT.
- (14) REPAIR AND EXTEND DOWNSPOUTS TO PROVIDE DRAINAGE AWAY FROM THE BUILDING. PAINT EXISTING PIECES THAT ARE REUSED.
- (15) CLEAN CAST STONE AROUND DOOR AND THRESHOLD.
- (16) REPAIR DOORS AND PAINT, INCLUDING WOOD TRIM. SEE DOOR SCHEDULE ON A601 FOR HARDWARE.
- (17) INSTALL PERMANENT DOOR STOP.
- (18) INSTALL LIGHT. SEE SCHEDULE.
- (19) RESTORE AND REINSTALL LAMPS. PAINT METAL AND PROVIDE NEW GLOBES.
- (20) REGRADE DISTURBED AREA AROUND BOTTOM OF STAIRS AND PIERS, REPLACE SOD.
- (21) INFILL OPENINGS WITH CONCRETE MASONRY UNITS.
- (22) WATERPROOF EXTERIOR OF BUILDING BELOW GRADE AND INFILL WHERE CONCRETE WAS REMOVED. SEE STRUCTURAL FOR EXTENT AND FILL REQUIREMENTS. SEE CIVIL FOR REGRADING.
- (23) TOILET FIXTURE. SEE SCHEDULE.
- (24) URINAL. SEE SCHEDULE.
- 25) SINK AND FAUCET. SEE SCHEDULE.
- (26) TOILET ROOM EQUIPMENT. SEE ELEVATIONS AND
- (27) TOILET ROOM PARTITIONS AND DOORS.
- (28) CONSTRUCT WALL.
- (29) DOOR. SEE SCHEDULE.
- (30) WINDOW. SEE SCHEDULE.
- (31) REINSTALL SALVAGED QUARRY TILE AND INSTALL NEW TILE WHERE NECESSARY.
- (32) PAINT METAL CORNICE AND PARAPET CAP.
- 33) REPAIR DAMAGE TO CONCRETE FROM PIPES AND CONDUIT. SEAL OPENING IN MASONRY AROUND
- (34) PAINT WOOD TRIM AND CORNICE OF BOW WINDOW
- (35) PAINT WOOD ON EXTERIOR SIDE OF EXISTING WINDOW/DOOR.
- (36) REPAIR WOOD AT BOTTOM OF CORNICE.
- (37) MODIFY THRESHOLD AND SEAL JOINTS.

 $\sum_{i} O_{i}$ \mathcal{O}_{\square} NALD OI

 \triangleleft

HaH Thompson Man, HVAC Upgrade, a

SOUTH CONSTRUCTION ELEVATION

A306

1 | SOUTH CONSTRUCTION ELEVATION

BASEMENT FLOOR

THIRD FLOOR

SECOND FLOOR

A307

Elevation: 0'-0"

FIRST FLOOR

Elevation: 0'-0"

Elevation: 0'-0"

Elevation: 0'-0"

ASSUME 10% REPOINTING OF ENTIRE BRICK FACADE UNLESS OTHER WORK IS NOTED.

NEW BRICK MASONRY RECONSTRUCT BRICK MASONRY 25% REPOINT 50% REPOINT 100% REPOINT CLEAN BRICK MASONRY CLEAN STONE/CAST STONE, REPOINT/SEAL JOINTS REPAIR CHIPPED CAST STONE REPOINT/SEAL JOINTS AT CAST STONE CONCRETE REPLACE HISTORIC CAST STONE REPAIR CRACK/HOLE IN CONCRETE/MASONRY

CONSTRUCTION KEY



(1) POUR CONCRETE FOOTINGS AND PIER BASE. (2) RESET STONE AT PORCH EDGE AND INSTALL

CONSTRUCTION NOTES

REPLACEMENT CAST STONE TO MATCH ORIGINAL.

(3) INSTALL DORIC COLUMNS AND REINSTALL SALVAGED

(4) REBUILD STAIR WALLS USING SALVAGED BRICK AND MATCHING REPLACEMENT BRICK WHERE NECESSARY. INSTALL REPLACEMENT CAST STONE CAPS TO MATCH ORIGINAL.

(5) REPLACE CAST STONE AT STAIRS AND TOP BAND AT PORCH. PAINT (DO NOT PAINT STEPS).

(6) REINSTALL STEPS.

(7) RECONSTRUCT CONCRETE WALK.

(8) INSTALL FLEXIBLE JOINT.

(9) CONSTRUCT NEW WALL AND INFILL AREA BENEATH STAIRS. SEE STRUCTURAL.

(10) INSTALL BALUSTRADE AND GUARDRAILS AT PORCH AND STEPS. INSTALL HANDRAILS AT STEPS.

(11) INSTALL PANELS AT PORCH OPENINGS.

(12) REPAIR AND PAINT SALVAGED WOOD FRAME AND INSTALL NEW PANEL IN PLACE OF MESH. REINSTALL.

(13) REPAIR WOOD ENTABLATURE, INCLUDING CORNICE, INSIDE OF FRIEZE, AND ARCHITRAVE, WITH CONSOLIDANT. PAINT.

(14) REPAIR AND EXTEND DOWNSPOUTS TO PROVIDE DRAINAGE AWAY FROM THE BUILDING. PAINT EXISTING PIECES THAT ARE REUSED.

(15) CLEAN CAST STONE AROUND DOOR AND THRESHOLD.

(16) REPAIR DOORS AND PAINT, INCLUDING WOOD TRIM. SEE DOOR SCHEDULE ON A601 FOR HARDWARE.

(17) INSTALL PERMANENT DOOR STOP.

(18) INSTALL LIGHT. SEE SCHEDULE.

(19) RESTORE AND REINSTALL LAMPS. PAINT METAL AND PROVIDE NEW GLOBES.

(20) REGRADE DISTURBED AREA AROUND BOTTOM OF STAIRS AND PIERS, REPLACE SOD.

(21) INFILL OPENINGS WITH CONCRETE MASONRY UNITS.

(22) WATERPROOF EXTERIOR OF BUILDING BELOW GRADE AND INFILL WHERE CONCRETE WAS REMOVED. SEE STRUCTURAL FOR EXTENT AND FILL REQUIREMENTS. SEE CIVIL FOR REGRADING.

(23) TOILET FIXTURE. SEE SCHEDULE.

(24) URINAL. SEE SCHEDULE.

(25) SINK AND FAUCET. SEE SCHEDULE.

(26) TOILET ROOM EQUIPMENT. SEE ELEVATIONS AND SCHEDULE.

(27) TOILET ROOM PARTITIONS AND DOORS.

(28) CONSTRUCT WALL.

(29) DOOR. SEE SCHEDULE.

(30) WINDOW. SEE SCHEDULE.

(31) REINSTALL SALVAGED QUARRY TILE AND INSTALL NEW TILE WHERE NECESSARY.

(32) PAINT METAL CORNICE AND PARAPET CAP.

(33) REPAIR DAMAGE TO CONCRETE FROM PIPES AND CONDUIT. SEAL OPENING IN MASONRY AROUND

(34) PAINT WOOD TRIM AND CORNICE OF BOW WINDOW

(35) PAINT WOOD ON EXTERIOR SIDE OF EXISTING WINDOW/DOOR.

(36) REPAIR WOOD AT BOTTOM OF CORNICE.

(37) MODIFY THRESHOLD AND SEAL JOINTS.

30% REVIEW SET

Thompson Man, HVAC Upgrade, a

WEST CONSTRUCTION ELEVATION

A307

1 WEST CONSTRUCTION ELEVATION

BASEMENT FLOOR

Elevation: 0'-0"

Hall Memorial Hale, and Addition

 \triangleleft

 $\sum_{i} O_{i}$

 Ω \square

NALD

OI



Start notes here






BUILDING

SECTIONS

A320

30% REVIEW SET



CONSTRUCTION KEY

NEW BRICK MASONRY

RECONSTRUCT BRICK MASONRY

25% REPOINT

50% REPOINT

100% REPOINT

CLEAN BRICK MASONRY

CLEAN STONE/CAST STONE, REPOINT/SEAL JOINTS

REPAIR CHIPPED CAST STONE

REPOINT/SEAL JOINTS AT CAST STONE

CONCRETE

REPLACE HISTORIC CAST STONE

REPAIR CRACK/HOLE IN CONCRETE/MASONRY

CONSTRUCTION NOTES

- 1) POUR CONCRETE FOOTINGS AND PIER BASE.
- 2 RESET STONE AT PORCH EDGE AND INSTALL REPLACEMENT CAST STONE TO MATCH ORIGINAL.
- (3) INSTALL DORIC COLUMNS AND REINSTALL SALVAGED
- (4) REBUILD STAIR WALLS USING SALVAGED BRICK AND MATCHING REPLACEMENT BRICK WHERE NECESSARY. INSTALL REPLACEMENT CAST STONE CAPS TO MATCH ORIGINAL.
- (5) REPLACE CAST STONE AT STAIRS AND TOP BAND AT PORCH. PAINT (DO NOT PAINT STEPS).
- 6 REINSTALL STEPS.
- (7) RECONSTRUCT CONCRETE WALK.
- (8) INSTALL FLEXIBLE JOINT.
- (9) CONSTRUCT NEW WALL AND INFILL AREA BENEATH STAIRS. SEE STRUCTURAL.
- (10) INSTALL BALUSTRADE AND GUARDRAILS AT PORCH AND STEPS. INSTALL HANDRAILS AT STEPS.
- (11) INSTALL PANELS AT PORCH OPENINGS.
- (12) REPAIR AND PAINT SALVAGED WOOD FRAME AND INSTALL NEW PANEL IN PLACE OF MESH. REINSTALL.
- (13) REPAIR WOOD ENTABLATURE, INCLUDING CORNICE, INSIDE OF FRIEZE, AND ARCHITRAVE, WITH CONSOLIDANT. PAINT.
- (14) REPAIR AND EXTEND DOWNSPOUTS TO PROVIDE DRAINAGE AWAY FROM THE BUILDING. PAINT EXISTING PIECES THAT ARE REUSED.
- (15) CLEAN CAST STONE AROUND DOOR AND THRESHOLD.
- (16) REPAIR DOORS AND PAINT, INCLUDING WOOD TRIM. SEE DOOR SCHEDULE ON A601 FOR HARDWARE.
- (17) INSTALL PERMANENT DOOR STOP.
- (18) INSTALL LIGHT. SEE SCHEDULE.
- (19) RESTORE AND REINSTALL LAMPS. PAINT METAL AND PROVIDE NEW GLOBES.
- (20) REGRADE DISTURBED AREA AROUND BOTTOM OF STAIRS AND PIERS, REPLACE SOD.
- (21) INFILL OPENINGS WITH CONCRETE MASONRY UNITS.
- (22) WATERPROOF EXTERIOR OF BUILDING BELOW GRADE AND INFILL WHERE CONCRETE WAS REMOVED. SEE STRUCTURAL FOR EXTENT AND FILL REQUIREMENTS. SEE CIVIL FOR REGRADING.
- (23) TOILET FIXTURE. SEE SCHEDULE.
- (24) URINAL. SEE SCHEDULE.
- (25) SINK AND FAUCET. SEE SCHEDULE.
- (26) TOILET ROOM EQUIPMENT. SEE ELEVATIONS AND
- (27) TOILET ROOM PARTITIONS AND DOORS.
- (28) CONSTRUCT WALL.
- (29) DOOR. SEE SCHEDULE.
- (30) WINDOW. SEE SCHEDULE.
- (31) REINSTALL SALVAGED QUARRY TILE AND INSTALL NEW TILE WHERE NECESSARY.
- (32) PAINT METAL CORNICE AND PARAPET CAP.
- (33) REPAIR DAMAGE TO CONCRETE FROM PIPES AND CONDUIT. SEAL OPENING IN MASONRY AROUND
- (34) PAINT WOOD TRIM AND CORNICE OF BOW WINDOW
- (35) PAINT WOOD ON EXTERIOR SIDE OF EXISTING WINDOW/DOOR.
- (36) REPAIR WOOD AT BOTTOM OF CORNICE.
- (37) MODIFY THRESHOLD AND SEAL JOINTS.

ONALD

 \mathcal{P}_{\square}

HoH Memorial H Thompson on, HVAC Upgrad Charles The Rehabilitation,

BUILDING SECTIONS

LOWER LEVEL RESTROOM ELEVATIONS -FIRST FLOOR RESTROOM ELEVATIONS -TO BE INCLUDED IN 60% SUBMISSION TO BE INCLUDED IN 60% SUBMISSION 30% REVIEW SET 1 INTERIOR ELEVATION 2 INTERIOR ELEVATION A400 1/4" = 1'-0"


Charles Thompson Memorial Hall Rehabilitation, HVAC Upgrade, and Addition

Interior ELEVATIONS

ADDITION - LOWER LEVEL ELEVATIONS -TO BE INCLUDED IN 60% SUBMISSION

SHEET NOTES

Start notes here



MACDONALD

A R C H I T

4 00 SOUTH FOURTH STREET STE 7 12 MINNEA
P 612 341 4051 . F 617 27 2 .

Charles Thompson Memorial Hall Rehabilitation, HVAC Upgrade, and Addition

Interior

ELEVATIONS


A401

30% REVIEW SET

ADDITION - FIRST FLOOR ELEVATIONS -TO BE INCLUDED IN 60% SUBMISSION 1 | INTERIOR ELEVATION

SHEET NOTES

Start notes here



Charles Thompson Memorial Hall Rehabilitation, HVAC Upgrade, and Addition

A402

Interior


ELEVATIONS

30% REVIEW SET

ADDITION - SECOND FLOOR ELEVATIONS -ADDITION - THIRD FLOOR ELEVATIONS -TO BE INCLUDED IN 60% SUBMISSION

SHEET NOTES

Start notes here




MACDONALD

A R C H I T

400 SOUTH FOURTH STREET STE 7 1 2 MINNEA

P 612 341 4051 . F 612 337 5843 .



Charles Thompson Memorial Hall Rehabilitation, HVAC Upgrade, and Addition


INTERIOR ELEVATIONS


EXTERIOR PORCH STAIRS ELEVATIONS -

TO BE INCLUDED IN 60% SUBMISSION

SHEET NOTES

Start notes here






Charles Thompson Memorial Hall Rehabilitation, HVAC Upgrade, and Addition


enlarged EXTERIOR ELEVATIONS

30% REVIEW SET A404




BALUSTER/GUARDRAIL AT PORCH

A503 1-1/2" = 1'-0"



2 HANDRAIL SECTION AT BALCONY BALUSTRADE

A503 | 1-1/2" = 1'-0"




3 HANDRAIL SECTION AT STAIR

A503 1-1/2" = 1'-0"

SHEET NOTES

Start notes here



ONALD

Charles Thompson Memorial Hall Rehabilitation, HVAC Upgrade, and Addition

PORCH DETAILS

- 1. MORTAR TO MATCH EXISTING IN TYPE, COLOR, TEXTURE, COMPOSITION, DIMENSION, AND PROFILE.
- 2. PROVIDE BRUSH FINISH TO SLIGHTLY EXPOSE MORTAR AGGREGATES.
- 3. SEE SPECIFICATIONS FOR HISTORIC MASON QUALIFICATIONS, MORTAR TESTING REQUIREMENTS, AND ADDITIONAL REPOINTING INFORMATION.

REMOVE TO DEPTH SPECIFIED, SEE SPECIFICATIONS - VERTICAL STONE SURFACES VARIES

REMOVE TO DEPTH SPECIFIED, SEE
SPECIFICATIONS

-HORIZONTAL STONE/CAST STONE SURFACES

PITCH MORTAR TO DRAIN FROM HORIZONTAL SURFACES

REMOVE TO DEPTH SPECIFIED, SEE **SPECIFICATIONS**

- VERTICAL BRICK SURFACES **→** VARIES

REMOVE TO DEPTH SPECIFIED, SEE

SPECIFICATIONS

HORIZONTAL BRICK SURFACES

STRIKE MORTAR FLUSH WITH BRICK

1 REPOINTING DETAILS

A504 | 1" = 1'-0"

2 | STAIR WALL RECONSTRUCTION

A504 | 1" = 1'-0"

MA C MACDONALD

A R C H I T

4 00 SOUTH FOURTH STREET STE 7 1 2 MINNEA

P 6 12 341 4051 . F 6 12 337 5843 .

Charles Thompson Memorial Hall Rehabilitation, HVAC Upgrade, and Addition

ROOF AND EXTERIOR REPAIR DETAILS

000000	Table of Contents
011000	Summary
012100	Allowances
012200	Unit Prices
012200	Alternates
012500	Substitution Procedures
012500	Contract Modification Procedures
012000	Project Management and Controls
013100	Construction Progress Documentation
013233	Photographic Documentation
013233	Submittal Procedures
013500	Historic Treatment Procedures
015000	
015000	Temporary Facilities and Controls
017300	Product Requirements Execution
017419	Construction Waste Management Closeout Procedures
017700	
017823	Operation and Maintenance
017839	Project Record Documents
017900	Demonstration and Training
033000	Cast-In-Place Concrete
040140.61	Stone Repair
040140.62	Stone Repointing
040310	Historic Masonry Cleaning
040322	Historic Brick Unit Masonry Repair
040323	Historic Brick Unit Masonry Repointing
052100	Steel Joist Framing
053100	Steel Decking
060312	Historic Wood Repair
061000	Rough Carpentry
061053	Miscellaneous Rough Carpentry
061063	Exterior Rough Carpentry
061516	Wood Roof Decking
061600	Sheathing
062013	Exterior Finish Carpentry
062023	Interior Finish Carpentry
064023	Interior Architectural Woodwork
070150.19	Preparation for Reroofing
072100	Thermal Insulation
072500	Weather Barriers
072600	Vapor Retarders
075323	Ethylene-Propylene-Diene-Monomer Roofing
077100	Roof Specialties

077200	Roof Accessories
078443	Joint Firestopping
079200	Joint Sealants
080152.93	Historic Treatment of Wood Windows
080314	Historic Treatment of Wood Doors
081433	Stile and Rail Wood Doors
084313	Aluminum-Framed Storefronts
085200	Wood Windows
087100	Door Hardware
087113	Automatic Door Operators
088300	Mirrors
090190	Maintenance of Painting and Coating
090320	Historic Treatment of Plaster
090391	Historic Treatment of Plain Plaster
090394	Historic Treatment of Decorative Plaster
090395	Historic Treatment of Artistic Plaster
092116.23	Gypsum Board Shaft Wall Assemblies
092216	Non-Structural Metal Framing
092900	Gypsum Board
093013	Ceramic Tiling
095123	Acoustical Tile Ceilings
096400	Wood Flooring
096513	Resilient Base and Accessories
096516	Resilient Sheet Flooring
096519	Resilient Tile Flooring
096813	Tile Carpeting
096816	Sheet Carpeting
097200	Wall Coverings
099113	Exterior Painting
099123	Interior Painting
099300	Staining and Transparent Finishes
102113.13	Metal Toilet Compartments
102113.16	Plastic-Laminate-Clad Toilet Partitions
102113.17	Phenolic-Core Toilet Compartments
102113.19	Plastic Toilet Compartments
012800	Toilet, Bath, and Laundry Accessories
104413	Fire Protection Cabinets
104416	Fire Extinguishers
142123.16	Machine Room-less Electric Elevators
142400	Hydraulic Elevators
321216	Asphalt Paving
321443	Porous Unit Paving
321713	Parking Bumpers
321723	Pavement Markings
328400	Planting Irrigation
329113	Soil Preparation
02/110	2011 Topmanon

329200 Turf and Grasses 329300 Plants



09/08/20

CHARLES THOMPSON MEMORIAL HALL MEP SCHEMATIC DESIGN NARRATIVE

MECHANICAL

Replace Existing Boilers

Replace the four existing modular boilers with new high-efficiency boilers of approximately 300 MBH capacity each. The new boilers will be Lochinvar Knight XL, or approved equal, with up to 96% efficiency rating.

Associated work to be completed in the Boiler Room includes:

- Replace hot water supply and return headers.
- Replace two existing zone heating pumps and add third pump for new addition.
- Install new air separator in hot water heating system.
- Install new side-stream filter and chemical feed in hot water heating system.
- Install new combustion air intakes and flues.
- Remove existing combustion air intake and breaching.

Insulate Existing Heating Piping in Boiler Room

Insulate all existing uninsulated hot water piping in the Boiler Room with fiberglass pipe insulation with all-purpose jacket, Knauf, or equal. Insulation thickness shall be in accordance with MN Energy Code.

Replace Existing HVAC Units for Assembly Hall, Dining Room and Basement

The existing split systems in the Assembly Hall, Dining Hall and Basement shall be replaced with new units. New rooftop units shall be installed for the Assembly Hall, and new split systems shall be installed for the Dining Room and Basement. Units shall be high efficiency, Carrier, Trane, or equal.

Existing Building Remodeling

Additional mechanical work in the existing building will include:

- Modify the existing heating systems as required for the areas of the building being remodeled. Provide new toilet exhaust systems for the toilet rooms.
- Provide air conditioning for the new office.

Building Addition

Complete HVAC systems shall be provided for the new building addition. These systems will include:

- A third hot water heating zone fed from the new boilers in the existing Boiler Room.
 Fintube radiation shall be provided along the exterior walls and windows, and a cabinet unit heater shall be provided at the new entrance.
- Air conditioning for the addition, with a new rooftop unit, ducted down for supply and return at the various floor levels.
- Ventilation for the new electrical room.

PLUMBING

Replace Existing Water Service

Replace existing water service with a new 6" water service to building. The new service will be utilized for a new sprinkler system in the building, as well as domestic water services.

It is anticipated at this time that the new water service will enter the building into the existing Boiler Room.

Remodel/New Toilet Rooms

The existing toilet rooms in the basement shall be remodeled with new plumbing fixtures and piping, based on new toilet room layout determined by Architect. It is anticipated that all existing plumbing fixtures will be replaced, as well as all existing water, waste and vent piping within the existing toilet rooms.

New plumbing systems shall be provided for the new toilet rooms on the First Floor.

FIRE PROTECTION

New Sprinkler System

A complete, new fire protection system shall be installed throughout the existing building and new addition. Piping layout shall be carefully designed, in conjunction with the fire protection subcontractor, in order to maintain the architectural character of the building.

ELECTRICAL

New Electrical Service

Replace existing electrical service with a new 3 phase service. It is anticipated at this time that the new electrical service will be 120/208 volt, 3 phase, 4 wire, 600 amps.

The new electrical service shall be brought into the new addition, and a new distribution panelboard installed. The existing building electrical system shall be back-fed from the new service. New electrical equipment shall be Square D, or equal.

Existing Building Remodeling

Electrical work within the existing building shall include:

- Re-feed new mechanical equipment.
- Lighting and power for remodeled toilet rooms in Basement.
- Lighting and power for new toilet rooms and office on First Floor.
- Lighting upgrades in Assembly Hall.

Building Addition

A complete electrical system shall be provided for the new building addition, including:

- Elevator power.
- Power for new mechanical equipment.
- Lighting and miscellaneous power.

FIRE ALARM SYSTEM

The existing fire alarm system shall be upgraded to current life safety code requirements, including incorporation of the new elevator.

END OF SCHEMATIC DESIGN NARRATIVE